

研華股份有限公司 Advantech Co., Ltd.

台北市內湖區瑞光路26巷20弄1號 No.1, Alley 20, Lane 26, Rueiguang Road Neihu, District, Taipei, Taiwan 114, R.O.C. Tel: 886-2-2792-7818 Fax: 886-2-2794-7301 www.advantech.com

IIoT Product Change Notice

The change will be applied on the ULI-246T (BB-485HESP). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

Note: The ordering process has not been changed. Customers should continue to order model number BB-.

1. Reason for the Change: Branding.

2. Affected Products: ULI-246T (BB-485HESP)

3. Impact on Application: No change to form, fit, or function.

, , , , , , , , , , , , , , , , , , , ,				
Item	Impact			
Impact on Mechanical Design	No			
Impact on Software Compatibility	No			
Impact on Environment Characteristics	No			
Impact on System Certifications	No			
Physical Outlook Change	Yes			
Ordering P/N Change	No			
Cut-in Implement	Component Running Change			

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ULI-246T BB-485HESP	20BB250- 10722-00	1990039155T010	Label	Old name plate High Energy Surge Protector [] Model 232HESP	Branding

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ULI-246T (BB-485HESP)	ECOM-194436	11/15/2022	Running Change	Update name plate

^{*}Note: Cut-in progress depends on factory production schedule.

Contact Windows

PM	Brian Foster / <u>brian.foster@advantech.com</u>
AE	N/A

^{**} Note: The ordering process has not been changed. Customers should continue to order model number BB-485HESP.