

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000913I

DATE: 06-Dec-2016

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX9038BABT+	N/A			Part reactivated from prior notice: M000869I
Reactivation	MAX9038BABT+T	N/A			Part reactivated from prior notice: M000869I
Reactivation	MAX9038BEBT+	N/A			Part reactivated from prior notice: M000813I
Reactivation	MAX9038BEBT+T	N/A			Part reactivated from prior notice: M000813I
Discontinuance	203-2859-22+	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	DS21Q58L-W+	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS2431P+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS2431X+UW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS2432X+UW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS2433AX+UW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS2433X-300-EC+UW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS26504+W	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E07P+W	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E15G+TW	DS28E15G+T	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E15G+UW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E15X-W20+1TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E35G-W23+1TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E80P+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E80P+W	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E80Q+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28E80Q+UW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28EL14Q-742+2TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28EL15Q+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS28EL15Q-742+7TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS33R11+W	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	DS3644B+W	N/A	06-Dec-2016	06-Dec-2016	The part was not released

Discontinuance	DS8500-JND+W	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	MAX28500GSE+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	MAX9214EUM+T	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9214EUM+TD	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9220EUM+	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9220EUM+D	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9220EUM+T	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9220EUM+TD	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9220EUM/V+	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9220EUM/V+T	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9234EUM+	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9234EUM/V+	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9238EUM+D	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9254EUM+D	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9254EUM+T	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9254EUM+TD	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9254EUM/V+	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9254EUM/V+T	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX9257EVKIT+	MAX9257AGCM/V+	06-Dec-2016	06-Dec-2016	EVKIT is No Longer Supported
Discontinuance	MAX9258EVKIT+	MAX9257AGTL/V+	06-Dec-2016	06-Dec-2016	EVKIT is No Longer Supported
Discontinuance	MAXQ636F-2591+W	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	MAXQ636V-2587+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	MAXQ636V-2605+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	MAXQ636V-2606+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	MAXQ636V-2614+TW	N/A	06-Dec-2016	06-Dec-2016	The part was not released
Discontinuance	VT1326SFC	N/A	06-Dec-2016	06-Dec-2016	Part can no longer be manufactured