



Product Obsolescence Notification

[GCM #10487302]

To: All active customers
From: Molex Micro Products Division
cc:
Date: December 29, 2010

Series / Product Family: 52808 series
Part Numbers Affected: See Attached sheet
Product Description: 1.0 FFC NON ZIF HSG ASSY EMBSTP PKG
Product Image: -
Replacements: See Attached sheet
Reason(s) for Obsolescence: Discontinuation of Lead Component
Last Order Entry Date: April 30, 2011
Obsolescence Effective Date: June 30, 2011

PCN Obsolescence special note:

If no last time buy orders are received by April 30, 2011.
Molex reserves the right to terminate production at any time at its own discretion. MOQ and lead time will be negotiated at time of order placement and will be dependent upon material availability. Molex will make all efforts to meet customer order requirements. Orders placed after Obsolescence Notification and subsequently cancelled will be subject to a cancellation charge.

2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747 FAX: 630-

www.molex.com

Part Numbers Affected	Replacement
528080491	528080471
528080590	528080570
528080690	528080670
528080890	528080870
528080991	528080971
528081090	528081070
528081290	528081270
528081291	528081271
528081490	528081470
528081491	528081471
528081590	528081570
528081790	528081770
528081791	528081771
528081890	528081870
528082690	528082670
528082691	528082671