



Product Change Notification

TE Connectivity

Product Change Notification: PCN-21-106163

PCN Date: 13-JUL-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

PRINTEASY SOFTWARE

Description of Changes

PARTS MADE OBSOLETE

Other attachments:

[PrintEasy Discontinuance Bulletin](#)

Reason for Changes:

PrintEasy v5 was released with support for Microsoft Operating Systems: Windows 2000, XP, 2003, Vista, 2008 and 7. With the withdrawal of support by Microsoft for Windows 7 in January 2020 the availability of platforms which support PrintEasy v5 has reduced to zero. As TE Connectivity (TE) cannot guarantee that PrintEasy v5 will continue to operate in Windows 10 (and future releases), it was regrettably decided to terminate support for PrintEasy v5.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

30-NOV-2021

First Date To Ship (Changed Parts Only):

Last Ship Date (Obsolete Parts Only):

22-DEC-2021

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CC6181-000	YES			"PEP-5-SUITE-DGLUSB", "2-1899350-3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CC6181-000	YES			"PEP-5-SUITE-DGLUSB", "2-1899350-3"			