

19<sup>th</sup> September 2016

From: Littelfuse Product Management

Subject: Change of carrier tape thickness pocket for 1206 series fuses

PCN number : 19092016


This is a 30-Day PCN.

This PCN affects only the below 3 series of fuses which we had recently acquired from TE,

- 1206SFH series
- 1206SFP series
- 1206SFS series

Affected part numbers are as per attached.

We are changing the tape size thickness of all our 1206 footprint fuses. Please see below on the tape thickness change. It impacts only the K0 dimension as shown in the below diagram.



The change as follows;

Product size and package change

	<b>Before change</b> mm(inch)	<b>After change</b> mm(inch)
Tape size thickness: K0	1.27 ± 0.10 (0.050 ± 0.004)	1.10 ± 0.10 (0.043 ± 0.004)

#### Dates and Timeframe

The effective start date of this notification is 19<sup>th</sup> October 2016 from our production.

Please go ahead to send to your customers the attachments.

Please forward to your team or anyone who needs this information. If you have any questions, please send an email to me without copying others.

Best regards;

Daniel Wang  
Director  
Global Product Management  
Electronics Business Unit  
[Dwang@Littelfuse.com](mailto:Dwang@Littelfuse.com)

**LFPCN19092016 Affected Parts List**

<b>Part Description</b>	<b>Part Number</b>
1206SFH100F/24-2	RF1585-000
1206SFH100FM/24-2	RF1752-000
1206SFH120F/24-2	RF1586-000
1206SFH120FM/24-2	RF1753-000
1206SFH150F/24-2	RF1587-000
1206SFH150FM/24-2	RF1754-000
1206SFH200F/24-2	RF1588-000
1206SFH200FM/24-2	RF1755-000
1206SFP100F/63-2	RF0453-000
1206SFP100FM/63-2	RF0462-000
1206SFP150F/63-2	RF0454-000
1206SFP150FM/63-2	RF0463-000
1206SFP200F/63-2	RF0455-000
1206SFP200FM/63-2	RF0464-000
1206SFP250F/32-2	RF0456-000
1206SFP250FM/32-2	RF0465-000
1206SFP300F/32-2	RF0457-000
1206SFP300FM/32-2	RF0466-000
1206SFP350F/32-2	RF0458-000
1206SFP350FM/32-2	RF0467-000
1206SFP400F/32-2	RF0459-000
1206SFP400FM/32-2	RF0468-000
1206SFP450F/32-2	RF0460-000
1206SFP450FM/32-2	RF0469-000
1206SFP500F/32-2	RF0461-000
1206SFP500FM/32-2	RF0470-000
1206SFP600F/24-2	RF2855-000
1206SFP600FM/24-2	RF2856-000
1206SFP700F/24-2	RF2857-000
1206SFP700FM/24-2	RF2858-000
1206SFP800F/24-2	RF2859-000
1206SFP800FM/24-2	RF2860-000
1206SFS100F/63-2	D23319-000
1206SFS100FM/63-2	RF0153-000
1206SFS125F/63-2	F11095-000
1206SFS125FM/63-2	RF0154-000
1206SFS150F/63-2	E77174-000
1206SFS150FM/63-2	RF0155-000
1206SFS200F/63-2	A03338-000
1206SFS200FM/63-2	RF0156-000
1206SFS250F/32-2	451674-000
1206SFS250FM/32-2	RF0157-000
1206SFS300F/32-2	799062-000
1206SFS300FM/32-2	RF0158-000
1206SFS350F/32-2	543268-000
1206SFS350FM/32-2	RF0159-000
1206SFS400F/32-2	F09837-000
1206SFS400FM/32-2	RF0160-000
1206SFS450F/32-2	A41268-000
1206SFS450FM/32-2	RF0161-000
1206SFS500F/32-2	E86727-000
1206SFS500FM/32-2	RF0162-000
1206SFS550F/24-2	A52099-000

1206SFS550FM/24-2  
1206SFS600F/24-2  
1206SFS600FM/24-2  
1206SFS700F/24-2  
1206SFS700FM/24-2  
1206SFS800F/24-2  
1206SFS800FM/24-2

RF0163-000  
C52564-000  
RF0164-000  
C57857-000  
RF0165-000  
F88154-000  
RF0166-000