



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Wednesday 22nd December, 2021

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following part numbers are now obsolete with immediate effect.

- M40-301xx46
- M40-401xx46
- **NOTE: M40-301xx46R and M40-401xx46R are not affected, and are still available**

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2021-12-22.xlsx

Unfortunately, we are no longer able to support this packing variation on these product ranges. Alternative items are available; please see the attached list for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team

technical@harwin.com

Obsolete Product Notification from Harwin

| Part number being made obsolete | Drawing for obsolete product | Last Time buy date | Alternative product | Drawing for alternative product |
|---------------------------------|--------------------------------------|--------------------|---------------------|---------------------------------|
| M40-3010246 | M40-301_obsolete.pdf | Immediate | M40-3010246R | M40-301R.pdf |
| M40-3010346 | M40-301_obsolete.pdf | Immediate | M40-3010346R | M40-301R.pdf |
| M40-3010446 | M40-301_obsolete.pdf | Immediate | M40-3010446R | M40-301R.pdf |
| M40-3010546 | M40-301_obsolete.pdf | Immediate | M40-3010546R | M40-301R.pdf |
| M40-3010646 | M40-301_obsolete.pdf | Immediate | M40-3010646R | M40-301R.pdf |
| M40-3010746 | M40-301_obsolete.pdf | Immediate | M40-3010746R | M40-301R.pdf |
| M40-3010846 | M40-301_obsolete.pdf | Immediate | M40-3010846R | M40-301R.pdf |
| M40-3010946 | M40-301_obsolete.pdf | Immediate | M40-3010946R | M40-301R.pdf |
| M40-3011046 | M40-301_obsolete.pdf | Immediate | M40-3011046R | M40-301R.pdf |
| M40-3011146 | M40-301_obsolete.pdf | Immediate | M40-3011146R | M40-301R.pdf |
| M40-3011246 | M40-301_obsolete.pdf | Immediate | M40-3011246R | M40-301R.pdf |
| M40-3011346 | M40-301_obsolete.pdf | Immediate | M40-3011346R | M40-301R.pdf |
| M40-3011446 | M40-301_obsolete.pdf | Immediate | M40-3011446R | M40-301R.pdf |
| M40-3011546 | M40-301_obsolete.pdf | Immediate | M40-3011546R | M40-301R.pdf |
| M40-3011646 | M40-301_obsolete.pdf | Immediate | M40-3011646R | M40-301R.pdf |
| M40-3011746 | M40-301_obsolete.pdf | Immediate | M40-3011746R | M40-301R.pdf |
| M40-3011846 | M40-301_obsolete.pdf | Immediate | M40-3011846R | M40-301R.pdf |
| M40-3011946 | M40-301_obsolete.pdf | Immediate | M40-3011946R | M40-301R.pdf |
| M40-3012046 | M40-301_obsolete.pdf | Immediate | M40-3012046R | M40-301R.pdf |
| M40-4010246 | M40-401_obsolete.pdf | Immediate | M40-4010246R | M40-401R.pdf |
| M40-4010346 | M40-401_obsolete.pdf | Immediate | M40-4010346R | M40-401R.pdf |
| M40-4010446 | M40-401_obsolete.pdf | Immediate | M40-4010446R | M40-401R.pdf |
| M40-4010546 | M40-401_obsolete.pdf | Immediate | M40-4010546R | M40-401R.pdf |
| M40-4010646 | M40-401_obsolete.pdf | Immediate | M40-4010646R | M40-401R.pdf |
| M40-4010746 | M40-401_obsolete.pdf | Immediate | M40-4010746R | M40-401R.pdf |
| M40-4010846 | M40-401_obsolete.pdf | Immediate | M40-4010846R | M40-401R.pdf |
| M40-4010946 | M40-401_obsolete.pdf | Immediate | M40-4010946R | M40-401R.pdf |
| M40-4011046 | M40-401_obsolete.pdf | Immediate | M40-4011046R | M40-401R.pdf |
| M40-4011146 | M40-401_obsolete.pdf | Immediate | M40-4011146R | M40-401R.pdf |
| M40-4011246 | M40-401_obsolete.pdf | Immediate | M40-4011246R | M40-401R.pdf |
| M40-4011346 | M40-401_obsolete.pdf | Immediate | M40-4011346R | M40-401R.pdf |
| M40-4011446 | M40-401_obsolete.pdf | Immediate | M40-4011446R | M40-401R.pdf |
| M40-4011546 | M40-401_obsolete.pdf | Immediate | M40-4011546R | M40-401R.pdf |
| M40-4011646 | M40-401_obsolete.pdf | Immediate | M40-4011646R | M40-401R.pdf |
| M40-4011746 | M40-401_obsolete.pdf | Immediate | M40-4011746R | M40-401R.pdf |
| M40-4011846 | M40-401_obsolete.pdf | Immediate | M40-4011846R | M40-401R.pdf |
| M40-4011946 | M40-401_obsolete.pdf | Immediate | M40-4011946R | M40-401R.pdf |
| M40-4012046 | M40-401_obsolete.pdf | Immediate | M40-4012046R | M40-401R.pdf |