


## **Product Change Notification (PCN)**

**PCN Number** 509487 Date Issued October 04, 2020 Reason for Change Obsolete Change Type Description This is to inform you that the part(s) referenced in this notice will be made obsolete. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s). Reason for Short Notice Force Majeure Planned Implementation Date October 13, 2020 Recommended Replacement Parts Please see the attached replacement parts list .xls file. Last Time Buy Date for Obsolete Parts October 13, 2020 Last Time Ship Date for Obsolete Parts October 13, 2020

Before Change





## After Change

- This is to inform you of an obsolescence due to a design modification made to the Searay tail aligner component as part of continued manufacturing improvements.
- Product Impact
  - No impact to fit, form or function.
- Part Number Impact
  - 45970-4915, replacement will be 45970-4916
- Qualification Reports and samples available upon request after the date shown above



## **Product Change Notification (PCN)**

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:509487" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com