

## Global Change Notification (GCN)

Product Family	HDAC	10723266	
		GCN Number	
Series	30700-124	November 04, 2015	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	This letter is to inform you that Molex is building new automated assembly process which will replace the existing manual process to increase capacity and meet customer requirements. This new assembly process with go through complete validation and testing as part of the qualification. PPAP documentation will be available on request.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-r	mail message.	
Reason For Short Notice Exception	New Capacity		
Assessment Of Change (How Product Will Be Qualified & Validated)	Product from new process will be validated and PPAP documentation will be available on request.		
Internal Molex Qualification Date (Planned Date Information Available)	December 04, 2015		
Sample Availability Date (Changed Part)	December 04, 2015		
Date of Implementation	December 18, 2015		
Method of Identifying Change	BLUE DOT		
Recommended Replacement Parts	NONE		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com