

## Product Advisory Notice

Issue Date: December 7, 2021

### **Advisory Type:**

Supply Chain Continuity

### **Description:**

Broadcom DCSG currently sources MegaRAID and HBA adapters from two contract manufacture (CM) locations:

- Sanmina in Thailand
- Flextronics in Malaysia

Currently, the 9560-16i/8i adapters are manufactured at Flextronics, but due to increased demand, Broadcom DCSG will begin sourcing these products from both CM locations. Broadcom is taking this step to ensure supply chain continuity as demand increases on the 95xx generation of adapters. There are no changes in component sourcing. The same vendors used at Flextronics for all components (PCBs, Memory, etc.) will be used by Sanmina.

### **Parts Affected:**

The following board models are subject to dual location sourcing. There will be no part number changes.

<b>Part Numbers</b>	<b>Model</b>	<b>Board Names</b>	<b>Description</b>
03-50077--XXabc 05-50077-XXabc	50077	9560-16i 9560-8i	SAS3916/3908 based MegaRAID adapters

The model number is the middle five digits of the part number and is the same for all adapter SKUs in that family.

- 03: indicates bulk level packaging
- 05: indicates kit level packaging
- XX indicates different SKUs of the same family
- abc indicates the minor revision level of the adapter

The actual board name and description may vary depending on the customer SKU description requirements



The CM location is traceable through the second letter of the board serial number:

- SPxxxxxxx – “P” indicates the board was manufactured at Sanmina in Thailand
- SKxxxxxxx – “K” indicates the board was manufactured at Flextronics in Malaysia



**Effect of Change:**

There is no change to form, fit or function. There will be no changes to part numbers or revisions.

No action is required unless customer SKU labeling needs to be changed to indicate assembly location. Please work with your Segment Marketing Lead to update custom labels as needed.

**Effective Date of Change:**

DCSG will begin dual sourcing from both CMs starting December 2021

---

The changes to these Broadcom parts have been reviewed and approved by Broadcom engineers and managers per Broadcom procedure: Change Control and Customer Notification A-5962-6052-80.

Please contact your Broadcom Inc. field sales engineer or Contact Center (<http://www.broadcom.com/contact/>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.

<b>Part Number</b>	<b>Part Description</b>
03-50077-00	9560-16i 8GB, GA, 00
03-50077-01	9560-8i 4GB, GA, 00
03-50077-04	9560-8i 4GB, 22, GA
03-50077-05	9560-8i 8GB, 22, GA
03-50077-06	9560-16i 8GB, 22, GA
03-50077-07	9560-16i 4GB, GA, 11 PRAID EP640i (Cougar6 4GB)
03-50077-08	9560-16i 8GB, GA, 11 PRAID EP680i (Cougar6 8GB)
03-50077-11	9560-16i 4GB, 02, GA (Shenandoah)
03-50077-12	9560-16i 4GB, 02, GA (Hightop MR Lite)
03-50104-01	9560-16i 4GB, 02, GA, Flattop Mezz Card MR Lite
05-50077-00	9560-16i SINGLE KIT, 8GB, GA, 00
05-50077-01	9560-8i SINGLE KIT, 4GB, GA, 00
05-50077-04	9560-8i 4GB, 22, GA, SINGLE KIT
05-50077-05	9560-8i 8GB, 22, GA, SINGLE KIT
05-50077-06	9560-16i 8GB, 22, GA, SINGLE KIT
05-50077-08	9560-16i 8GB, 12, GA TF KIT
P3-50077-08	9560-8i 8GB 22 EVT (SR17A32433)
P3-50077-09	9560-8i 4GB 22 EVT (SR17A32429).
P3-50077-11	L3 DVT Assembly, Aero: 9560-16i, 8GB
P3-50077-13	L3 DVT Assembly, Aero: 9560-8i, 8GB
P3-50077-14	L3 DVT Assembly, Aero: 9560-8i, 4GB
P3-50077-15	Aero: 9560-16i, 4GB, HPE Shenandoah
P3-50077-18	SAS 9560-8i 4GB 22 DVT (SR17A32430)
P3-50077-19	SAS 9560-8i 8GB 22 DVT (SR17A32434)
P3-50077-20	SAS 9560-16i 8GB 22 DVT (SR17A32438)
P3-50077-21	9560-16i, 4GB, HPE Shenandoah MR Lite
P3-50077-22	SAS 9560-16i 8GB 12 PVT (RS3P4TF160F)
P3-50077-28	9560-8i 4GB 22 PVT (SR17A32431)
P3-50077-29	9560-8i 8GB 22 PVT
P3-50077-30	9560-16i 8GB 22 PVT (SR17A32439)
P3-50077-31	Aero: 9560-16i, 4GB, HPE (MR), DVT2
P3-50077-32	Aero: 9560-16i, 4GB, HPE (MR Lite), DVT2
P5-50077-01	9560-16i 8GB, 12, PVT (RS3P4TF160FSP)
03-50077-13	9560-8i 4GB, 07, GA
05-50077-09	9560-8i SINGLE KIT, 4GB, 07, GA
03-50077-18	9560-16i 4GB 22 GA
05-50077-10	9560-16i SINGLE KIT, 4GB, 22, GA
03-50077-23	9560-8i 4GB, 11, GA
03-50077-25	9560-16i 4GB 22 GA WS (SR11E89791)
05-50077-16	9560-16i 4GB, 22, GA, WS (5R11B66432)
03-50077-28	9560-16i 8GB, 02, GA, MR416i-p Gen11