

## Global Change Notification (GCN)

Product Family 1.0 FFC CONN NON ZIF SMT (R/A) 10685928

GCN Number

Series 52852 May 14, 2015

Date Issued

Reason For Change Outsourcing Component Or Subcomponent

Change Description The purpose of this letter is to add Linear Precision Manufacturing Pte. Ltd. as additional manufacturing location for 52852 housing series. The reason is to make sure there is assurance of supply for 52852 parts. This changes only apply to Molex Malaysia plant. The material is produce per Molex specification. There is no change in design and process for Molex Malaysia, therefore no change in the Molex assembly part number will occur either. Sample can be provided upon request. First article inspection will be done. The implementation will be running change.

--	--

Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception New Capacity

Assessment Of Change (How Product Will Be Qualified & Validated) Based on first Article Inspection

Internal Molex Qualification Date (Planned Date Information Available) May 20, 2015

Sample Availability Date (Changed Part) May 21, 2015

Date of Implementation June 27, 2015

Method of Identifying Change Based on label information

Recommended Replacement Parts Not applicable

Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)