

Enclustra - Product Change Notification (PCN)

No.:	PCN_SP_2021-18
Date:	08.12.2021

Affected Products	
Product Series	Mercury+ XU7
Affected Product Model	All product models
Affected Parts	All parts R3
Replacement Parts	All parts R4

Type of PCN, Description and expected impact for customers		
	A – Post on Enclustra Website	
Type of PCN	☐ Removal of Product Model (if no customer is affected)	
	☐ Minor Revision without impact on customer	
	☐ Other, specify:	
	B – Inform current customers	
	☐ Increase of minimum order quantity (MOQ)	
	☐ Status Changes to end-of-life (EOL)	
	☐ Removal of Product Model (if customer is affected)	
	☐ Major Revision roll-out	
	☐ Minor Revision with impact for customer	
	☐ Other, specify:	
	C – Inform all affected customers	
	☐ Security related bug / Major non-conformance to specification	
	☐ Other, specify:	
Description of change	Improved signal integrity on MGT B230	
	Fixed issues on Ethernet performance at high temperatures	
	Change of the battery voltage LDO	
	Pinout changes on voltage monitoring outputs	
Reason for change	Bug fixes and improvements	
Expected impact on customer	After stock depletion of affected parts (R3), only revision R4 parts will be delivered.	
Forecasted key milestones	None	

Details of change	
Details	Refer to "Mercury+ XU7 R4 Known Issues and Changes" document available on Enclustra download site.

Contact

Details

If you have any questions or require additional information, please contact $\underline{info@enclustra.com}$.

Web: www.enclustra.com

Template No: ED42010-02 Page 1 of 1