

# **TE Connectivity**

## Product Change Notification: P-22-023037

PCN Date: 13-JUL-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

## General Product Description: INTERFACE SEAL FOR 2W HP CONNECTOR

#### **Description of Changes**

Manufacturing location change. Following Part Numbers will be transferred from < TE Connectivity San Salvo> to <TE Connectivity Esztergom>.Mold involved is:21-0067687 that produce the component 1801156-1 used on Finished good:1-1801175-1 1-1801175-2; 1-1801175-3; 1-1801175-4; 1-1801175-5; 1-1801175-6; 1-1801175-7; 1-1801175-8; 1-1801175-9; 1801175-1; 1801175-2; 1801175-3; 1801175-4; 1801175-5; 1801175-6; 1801175-7; 1801175-8; 1801176-1; 1801176-2; 1801176-2; 1801176-4; 1801176-5; 1801176-6; 1801176-7; 1801176-8; 1801176-9; 9-1801175-7; 9-1801175-8; 9-1801175-9; 9-1801175-6; 9-1801175-5; 2278069-1; 2278069-2; 2289836-1; 2289836-2; 2278361-1; 2278361-2; 2278361-3; 2278361-4; 2298251-1; 2298251-2; 2298278-1; 2298278-2; 2298283-1; 2298283-2; 2299026-1; 2299026-2; 2278364-1; 2278364-2; 2278170-1; 2278170-2; 2278170-3; 2278170-4; 2310454-1;

### Reason for Changes:

Dear Customer, we hereby inform you about a transfer of tools. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. A PPAP Level 1 will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN

estimated Dates:				
Last Order Date (Obsolete Parts Only):	y): First Date To Ship (Changed Parts Only):			
	10-OCT-2022			
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):			
	16-OCT-2022			

#### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1-1801175-1</u>	NO						
<u>1-1801175-2</u>	NO						
<u>1-1801175-3</u>	NO						
1-1801175-4	NO						
<u>1-1801175-5</u>	NO						
<u>1-1801175-6</u>	NO						
<u>1-1801175-7</u>	NO						
<u>1-1801175-9</u>	NO						
<u>1801175-1</u>	NO						
<u>1801175-2</u>	NO						
<u>1801175-3</u>	NO						
<u>1801175-4</u>	NO						
<u>1801175-5</u>	NO						
<u>1801175-6</u>	NO						
<u>1801175-7</u>	NO						
<u>1801176-1</u>	NO						
<u>1801176-3</u>	NO						
<u>1801176-5</u>	NO						
<u>1801176-8</u>	NO						