

October 15th, 2019

To: Valued Customer

From: Littelfuse Product Management

Subject: Additional supply of 354 and 358 series fuses

With regards to the above reference, Littelfuse is currently supplying 354 and 358 series fuses from Europe.

With the expectation of reducing the lead time and assurance of supply, Littelfuse would be looking at supporting future needs from our Plant in Suzhou (China) as well. It will be effective starting December 15th, 2019.

The part numbers remain the same. There is no change on Form, Fit, or Function.

Affected Part Numbers		
35401000029	35414000029	
35402000029	35415000029	
35402500029	35416300029	
35406300029	35418000029	
35408000029	35421000029	
35411000029	35813150029	
35411250029	35814000029	
35411600029	35815000029	
35412000029	35816300029	
35412500029	35818000029	
35413150029	35821000029	

In order to aid in tracking, identical parts may be marked with or without the letter "Z".

Here below shows the marking on fuse caps.

ltem	Current	Plan
Cap1	F1A440V 😧	F1A440V Z 😧
Cap2	cURus V	cURus V

Please let us know, should you require any support or have any further queries

Ben Zheng Global Product Manager Electronics Business Unit Littelfuse Europe GmbH +49 16090123815 BZheng@Littelfuse.com