



Product Change Notification

TE Connectivity

Product Change Notification: E-07-008812-C

PCN Date: 12-OCT-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMPMODU MTE Vertical Surface Mount Headers

Description of Changes
Changing the housing material on the lead-free assembly P/N's to accommodate a 260 degrees C solder reflow temperature

Reason for Cancellation:
Action was not taken at that time (2207) as noted on the ECR. The ECR was never completed, so it is being cancelled at this time.

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5-1375549-3 | NO | | | | | | |
| 5-1375549-3 | NO | | | | | | |
| 5-1375549-3 | NO | | | | | | |
| 5-1375549-3 | NO | | | | | | |
| 5-1375549-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |
| 5-1375582-4 | NO | | | | | | |
| 5-1375582-4 | NO | | | | | | |
| 5-1375582-5 | NO | | | | | | |
| 5-1375582-5 | NO | | | | | | |
| 5-1375582-5 | NO | | | | | | |
| 5-1375582-5 | NO | | | | | | |
| 5-1375582-7 | NO | | | | | | |
| 5-1375582-7 | NO | | | | | | |
| 5-1375582-9 | NO | | | | | | |
| 5-1375582-9 | NO | | | | | | |
| 5-1375583-1 | NO | | | | | | |
| 5-1375583-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5-1375549-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5-1375549-3 | NO | | | | | | |
| 5-1375582-4 | NO | | | | | | |
| 5-1375583-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5-1375549-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |
| 5-1375582-4 | NO | | | | | | |
| 5-1375582-5 | NO | | | | | | |
| 5-1375583-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5-1375549-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |
| 5-1375582-5 | NO | | | | | | |
| 5-1375582-7 | NO | | | | | | |
| 5-1375582-8 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5-1375549-3 | NO | | | | | | |
| 5-1375582-3 | NO | | | | | | |
| 5-1375582-5 | NO | | | | | | |
| 5-1375582-7 | NO | | | | | | |
| 5-1375582-8 | NO | | | | | | |