

# Product Obsolescence Memo

## INDUCTIVE COMPONENTS

April, 2015

### **Bourns® Model 73F Series Axial Lead Varnished Chokes to be Discontinued**

Bourns has decided to discontinue the Bourns® [Model 73F Series](#) Axial Lead Varnished Chokes. A lack of sales volume and diminishing demand necessitates this action. Regrettably, there are no replacement part numbers available at this time.

Obsolete Part Numbers		
73F104AF-RC	73F564AF-RC	73F273AF-RC
73F124AF-RC	73F684AF-RC	73F333AF-RC
73F154AF-RC	73F824AF-RC	73F393AF-RC
73F184AF-RC	73F103AF-RC	73F473AF-RC
73F224AF-RC	73F123AF-RC	73F563AF-RC
73F274AF-RC	73F153AF-RC	73F683AF-RC
73F334AF-RC	73F183AF-RC	73F823AF-RC
73F394AF-RC	73F223AF-RC	73F102AF-RC
73F474AF-RC		

Please plan for the following deadlines:

*Last time buy date: October 31, 2015*

*Last time ship date: April 30, 2016*

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).