

## **Product Change Notification (PCN)**

PCN Number	508551	Date Issued	March 26, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	April 20, 2020		
Sample Availability Date (Changed Part)	April 20, 2020		
Planned Implementation Date	April 30, 2020		
Method of Identifying Change	No special marking on the product or packaging		
Before Change	After Change		
	Overview To improve crimp connection quality Molex decided to change terminal. Product Impact Two spring terminal has better connection properties		

Terminal with one spring will be changed to terminal with two springs

- Part Number Impact
- See attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above

## molex

**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508551**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com PCN # Molex Part # 508551 1210560007 508551 1210560023