


## Product Discontinuation Notice

January 2013

### Discontinuation of NaPiCa (SMD & Chip) Light Sensor



**1. Reason:** Low market demand

**2. Affected parts:**

AMS1000  
AMS4000

**3. Last time buy:** End of September 2013

**4. Substitution:** Contact your local Panasonic sales representative

Any questions, please contact your local Panasonic Sales representatives.

(Ref#: T-1289-07)