

TE Connectivity

Product Change Notification: P-21-020596 PCN Date: 10-MAR-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

SFR Very Flexible, Flame-Retardant, Silicon Elastomer Tubing and SEB Raychem Side Entry Bushing

Description of Changes

SFR tubing sizes 3/8 and larger passed fungus resistance testing and are released for sale to the RT-1140 and AS23053/10 specifications. All sizes of SEB products are also released for sale. SFR tubing sizes 1/4 and smaller will continue to be sold only on deviation until TE can ensure they will meet the fungus resistance requirements of AS23053/10.

Other attachments:

Part Numbers and Descriptions of Affected SEB and SFR Products

Reason for Changes:	
Part status change.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	12-MAR-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5660024001	NO			"6-1194469-7", "SFR-3/8-0-SP"			
5660034001	NO			"7-1194469-4", "SFR-1/2-0-SP"			
5660044001	NO			"8-1194469-2", "SFR-5/8-0-SP"			
5660054001	NO			"8-1194469-7", "SFR-3/4-0-SP"			
<u>5660064004</u>	NO			"9-1194469-4", "SFR-7/8-0-SP"			
5660074001	NO			"9-1194469-8", "SFR-1- 0-SP"			
CS9492-000	NO			"SEB-C"			
CS9493-000	NO			"SEB-D"			
CS9495-000	NO			"SEB-F"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>5660024001</u>	NO			"6-1194469-7", "SFR-3/8-0-SP"			
5660034001	NO			"7-1194469-4", "SFR-1/2-0-SP"			
5660044001	NO			"8-1194469-2", "SFR-5/8-0-SP"			
5660054001	NO			"8-1194469-7", "SFR-3/4-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>5660064004</u>	NO			"9-1194469-4",			
				"SFR-7/8-0-SP"			
FCC0074001	NO			"9-1194469-8", "SFR-1-			
<u>5660074001</u> N	NO	NO		0-SP"			
CS9492-000	NO			"SEB-C"			
CS9493-000	NO			"SEB-D"			
CS9495-000	NO			"SEB-F"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5660034001	NO			"7-1194469-4", "SFR-1/2-0-SP"			
5660044001	NO			"8-1194469-2", "SFR-5/8-0-SP"			
5660054001	NO			"8-1194469-7", "SFR-3/4-0-SP"			
5660064004	NO			"9-1194469-4", "SFR-7/8-0-SP"			
5660074001	NO			"9-1194469-8", "SFR-1- 0-SP"			

Part Numbers and Descriptions for SEB and SFR products affected by this PCN, issued March 10, 2021:

Part Number	Part Description
CS9490-000	SEB-A
CS9491-000	SEB-B
CS9492-000	SEB-C
CS9493-000	SEB-D
CS9494-000	SEB-E
CS9495-000	SEB-F
5660024001	SFR-3/8-0-SP
5660034001	SFR-1/2-0-SP
5660044001	SFR-5/8-0-SP
5660054001	SFR-3/4-0-SP
5660064004	SFR-7/8-0-SP
5660074001	SFR-1-0-SP
5660084001	SFR-1-1/4-0-SP
5660094006	SFR-1-1/2-0-SP
5660174002	SFR-1-3/4-0-SP
5660114004	SFR-2-0-SP