Product Discontinuation



PD_107_19

Last Order Date: 2019-12-15Last Delivery Date: 2020-06-15

Reason: The TLE7262E and TLE7263E components had "Not For New Design" (NFND) status since 2016. The TLE9262BQX component, featuring 2x LDO, 1x CAN, 1x LIN, 4x High-Side Switches, has been released to production back in July 2017, as part of the "Mid-Range+ SBC" product family.

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
TLE7262E	SP001137586	TLE7262EXUMA2	PG-DSO-36	TLE9262BQX	SP001611036	TLE9262BQXXUMA1	PG-VQFN-48
TLE7263E	SP001130182	TLE7263EXUMA2	PG-DSO-36	TLE9262BQX	SP001611036	TLE9262BQXXUMA1	PG-VQFN-48

If you have any questions, please do not hesitate to contact your local sales office.