PCN Number:	201605230		005		PCN Da		te:	5/27/2016	
Title: Datasheet for	LM2758								
<b>Customer Contact:</b>	PCN Manager			<b>Dept:</b> Qua			ity Services		
Change Type:									
Assembly Site			Design			Wafer	Bum	o Site	
Assembly Process			Data Sheet					o Material	
Assembly Materials		Щ	Part number change	<u>                                     </u>	Ц			Process	
Mechanical Specification		Ц	Test Site	1 -	╣		afer Fab Site		
Packing/Shipping/	Labeling		Test Process	╂╞	4			Materials	
			LiciLi Dataila			Wafer	Fab F	rocess	
Notification Details									
Description of Chang			ouncing an information or	. 1		L:C: L:	_		
TORGO INSCIAMIENTO INCO	i poracca is t	u1111	canoning an information of	, 1		ciricatioi	•••		
The product datasheet(	(s) is being u	ıpda	ited as summarized below	<i>1</i> .					
The following change h	istory provid	les 1	further details						
The following change in	istory provid	103	artifici actalis.			-			
<b>TEXAS</b>								I M2750	
INSTRUMENTS	INSTRUMENTS  LM2758  SNVS551E – APRIL 2008 – REVISED MAY 2016								
Channes from Basisian B (N	In. (0040) to David			0.110		- / 1112 200			
Changes from Revision D (N	1ay 2013) to Revi	151011						Page	
<ul> <li>Added Device Information and Pin Configuration and Functions sections, ESD Ratings table, Feature Description, Device Functional Modes, Application and Implementation, Power Supply Recommendations, Layout, Device and Documentation Support, and Mechanical, Packaging, and Orderable Information sections</li></ul>									
The datasheet number	will be chang	ging							
Device Family			Change From:					ge To:	
LM2758	SNVS551D					SNVS551E			
These changes may be <a href="http://www.ti.com/production">http://www.ti.com/production</a>			datasheet links provided.						
Reason for Change:									
To more accurately refl	ect device ch	nara	icteristics.						
			nction, Quality or Relia						
No anticipated impact. to the actual device.	This is a spe	cific	cation change announcem	ent	or	nly. The	re ar	e no changes	
Changes to product identification resulting from this PCN:									
None.							· <u> </u>		
<b>Product Affected:</b>									
LM2758TLX/NOPB	LM2758TL/	NO	РВ						

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com