

TE Connectivity

Product Change Notification: P-20-019266 PCN Date: 07-JUL-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Laser marking process on modules DMC-M

Description of Changes

Te Evreux, FR will implement a new process for the cavity marking, and the part number marking on module DMC-M. Technical risk: referring to the declaration of design and perfomances DDP 732 313 VA, the technical risks have been highlighted These have been mitigated thanks to the qualification test report PVE 732-193 VA. Pending approval from certication authoritiy

Reason for Changes:

Product improvement. Laser marking process will avoid, customer and internal quality alert issue due to current marking process. Current process is ink marking (legibility and marking erase). The marking of the cavities will be made at the end of the assembly process. It will avoid to have two part number for the grommet (rear male and rear female grommet). Laser proces avoid "wet" processes: no managment of peremption dates of ink, no time waisted du to curing process.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):				
	20-JUL-2020				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	20-JUL-2021				

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
ZPF000000000015185	NO			"DMC-M 04-12 AN"			
ZPF000000000015191	NO			"DMC-M 04-12 BN"			
ZPF000000000015233	NO			"DMC-M 08-16 PN"			
ZPF000000000015275	NO			"DMC-M 12-20 SN"			
ZPF000000000015291	NO			"DMC-M 20-22 AN", "BACI10BC2022PNB"			
ZPF000000000015299	NO			"DMC-M 20-22 BN"			
ZPF000000000015306	NO			"DMC-M 20-22 PN"			
ZPF000000000015318	NO			"DMC-M 20-22 SN"			
ZPF000000000099564	NO			"732-8254-99"			
ZPF0000000000099565	NO			"732-8256-99"			
ZPF0000000000099684	NO			"DMC-M 99-01 PN"			
ZPF0000000000099685	NO			"DMC-M 99-01 SN", "73208770147000B"			
ZPF0000000000099705	NO			"DMC-M 99-01 BN", "BACI10BC1622SNB"			
ZPF000000000100304	NO			"732-8254-22"			
ZPF000000000100306	NO			"732-8256-22"			
ZPF000000000110281	NO			"732-8255-22"			
ZPF0000000000202708	NO			"DMC-MR 30-23 PN"			

Part Number(s) being Modified:

	Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-	PF000000000015185	NO			"DMC-M 04-12 AN"			
	PF000000000015191	NO			"DMC-M 04-12 BN"			
-	PF000000000015233	NO			"DMC-M 08-16 PN"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
ZPF000000000015275	NO			"DMC-M 12-20 SN"			
ZPF000000000015291	NO			"DMC-M 20-22 AN", "BACI10BC2022PNB"			
ZPF000000000015299	NO			"DMC-M 20-22 BN"			
ZPF000000000015306	NO			"DMC-M 20-22 PN"			
ZPF000000000015318	NO			"DMC-M 20-22 SN"			
ZPF000000000099564	NO			"732-8254-99"			
ZPF000000000099565	NO			"732-8256-99"			
ZPF000000000099684	NO			"DMC-M 99-01 PN"			
ZPF000000000099685	NO			"DMC-M 99-01 SN", "73208770147000B"			
ZPF000000000099705	NO			"DMC-M 99-01 BN", "BACI10BC1622SNB"			
ZPF000000000100304	NO			"732-8254-22"			
ZPF000000000100306	NO			"732-8256-22"		•	
ZPF000000000110281	NO			"732-8255-22"			
ZPF000000000202708	NO			"DMC-MR 30-23 PN"		•	

Part Number(s) being Modified:

Part Number	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
	per PCN	Drawing	Number		Number	Part Number(s)	Difference
ZPF000000000015233	NO			"DMC-M 08-16 PN"			
ZPF000000000015291	NO			"DMC-M 20-22 AN",			
ZFF000000000013291	NO			"BACI10BC2022PNB"			
ZPF000000000015306	NO			"DMC-M 20-22 PN"			
ZPF000000000015318	NO			"DMC-M 20-22 SN"			
ZPF000000000099564	NO			"732-8254-99"			
ZPF000000000099565	NO			"732-8256-99"			
ZPF000000000099684	NO			"DMC-M 99-01 PN"			
ZPF000000000099685	NO			"DMC-M 99-01 SN",			
	_			"73208770147000B"			
ZPF0000000000099705	NO			"DMC-M 99-01 BN",			
				"BACI10BC1622SNB"			
ZPF000000000100306	NO			"732-8256-22"			
ZPF000000000110281	NO			"732-8255-22"			
ZPF000000000202708	NO			"DMC-MR 30-23 PN"			