

Product Change Notification Form

PCN Number: 20180410-01	Rev: A	Date: 04/10/18
--------------------------------	---------------	-----------------------

Summary of Change: USB-ICP-80C51ISP, USB-ICP-LPC2K, USB-ICP-LPC9XX & USB-ICP-SAB9 are all being discontinued.

Reason for Change: Parts are no longer available.

Detailed Description of Change:

The USB-ICP-80C51ISP, USB-ICP-LPC2K, USB-ICP-LPC9XX & USB-ICP-SAB9 are all being discontinued. After available stock at distributors is depleted, it will not be refilled.

Products Affected:

Affected Product	Recommended Replacement Product
USB-ICP-80C51ISP	NONE
USB-ICP-LPC2K	NONE
USB-ICP-LPC9XX	NONE
USB-ICP-SAB9	NONE

Forecasted Key Dates and Milestones:

04/10/18 PCN Date, the date this document was released for distribution to customers and distributors.

Reference Documents and Attachments:

FDI Contacts:

For additional information or details please contact any of our franchised Distributors including Avnet, Digi-Key and Mouser. Or contact the Product Team at FDI directly via email at support@teamfdi.com or via phone at 256-883-1240 or fax at 256-883-1241.