

TE Connectivity

Product Change Notification: E-18-011654 PCN Date: 01-AUG-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:	
M Series Connector Strain Relief	

Description of Changes	
Supersede 201237-1 with 201237-2	

Reason for Changes:						
Discontinuance. 201237-1 and 201237-2 have been identical RoHS compliant parts since 2008. Prior to 2008 201237-1 was not RoHS compliant. It does not make business sense to maintain both mart numbers.						
Estimated Dates:						
Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):						
31-OCT-2018						
Last Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only):						
30-APR-2019	No Mixed Shipments					

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
201237-1	YES				201237-2		RoHS compliant part
201237-1	YES				201237-2		RoHS compliant part

Part Number(s) being Modified:

Part	Part Discontinued per PCN	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number		Drawing	Number	Number(s)	Number	Number(s)	Difference
201237-1	YES				201237-2		RoHS compliant part

Part Number(s) being Modified:

Part	Part Discontinued per PCN	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number		Drawing	Number	Number(s)	Number	Number(s)	Difference
201237-1	YES				201237-2		RoHS compliant part