

ASSMANN WSW components, Inc. 1840 W. Drake Drive, Suite 101 Tempe, AZ 85283 Toll Free 877.277.6266 www.assmann.us

## **Product Change Notification (PCN)**

Issue Date: 5/2/2014 Modification/Revision Date: 5/2/2014

## IDC

Change Notification:	PCN-US-20140502-IDC
Description of changes:	Change of Production Location Change of Part Numbers
	"-R" is removed from old part number
	<b>INVENTORY ACTION</b> Inventories at ASSMANN WSW will be shipped per our standard shipping algorithm. Customers may receive either part number through transition until the old part number is consumed.
Date of change and Implementation:	Change: 5/2/2014
Key Characteristics of Change:	Change of part number
Products Affected:	
	Parts listed below
Reason for Change:	Part number unification
Response:	No response to this notification is required.



ASSMANN WSW components, Inc. 1840 W. Drake Drive, Suite 101 Tempe, AZ 85283 Toll Free 877.277.6266 www.assmann.us

## Product Change Notification (PCN)

Issue Date: 5/2/2014 Modification/Revision Date: 5/2/2014

## **Reference Documents / Attachments:**

**Document: Drawing** 

Previous part number	New part number	Drawing number
AWH34G-0232-T-R	AWH-34G-0232-T	ASS_2310_COrev09
AWH50G-0232-T-R	AWH-50G-0232-T	ASS_2310_COrev09
AWP40-8540-T-R	AWP-40-8540-T	ASS_2261A_COrev01
AWP34-7540-T-R	AWP-34-7540-T	ASS_1194C_COrev06
AWP2-26-7240-T-R	AWP2-26-7240	ASS_2309_COrev06