

Expertise Applied | Answers Delivered

8755 W. Higgins Road Suite 500 Chicago, IL 60631

www.littelfuse.com

Subject: Notice Of Obsolescence - Series 70 Series Fuses

Document# LFPCN PG0061

Date: 10/29/2015

This letter is to inform Littelfuse Sales, Sales Support & Customers of the obsolescence of our Series 70 Alarm Indicating Fuses. Obsolescence is due to the vendor no longer producing the fuses. There are no replacement fuses available, so this series will no longer be marketed. Any orders that can be supported with our limited inventory shall be fulfilled; however, our inventory cannot be replenished. This change is effective immediately.

Affected Part Numbers		
70A00000Z	70G00000Z	70P00000Z
70B00000Z	70H00000Z	70R00000Z
70C00000Z	70J00000Z	70S00000Z
70D00000Z	70K00000Z	70X00000Z
70E00000Z	70M00000Z	
70F00000Z	70N00000Z	

Please update your systems accordingly and thank you for your business. We apologize for any inconveniences.

Thank you for your continued business.



Expertise Applied | Answers Delivered

## Jim McGuire

Assistant Product Manager, North America Electrical Business Unit, POWR-GARD Products Littelfuse, Inc.

Tel: +1 773-628-1000 Fax: +1 773-830-1797 Direct: +1 773-628-0708 Mobile: +1 773-206-7775 Tech: +1 800-TEC-FUSE

www.littelfuse.com/electrical

Littelfuse electrical fuse and protection relay portfolio includes:











Expertise Applied | Answers Delivered

8755 W. Higgins Road Suite 500 Chicago, IL 60631

www.littelfuse.com