



TE Connectivity

Product Change Notification: E-17-010621 PCN Date: 04-SEP-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Obsolete AMP-DUAC (Part 3)

Description of Changes

Dear Customers, TE Connectivity is ending the AMP-DUAC product family. We apologize for any inconveniences this may cause but many AMP-DUAC offerings have VAL-U-LOK equivalents. [AMP-DUAC = VAL-U-LOK], [794576 = 794955], [794576 = 794955], [794575 = 1586314], [794578 = 794957], [794579 = 1586316].

Reason for Changes:	
Discontinuance.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
30-OCT-2019	
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
31-DEC-2019	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
794577-1	YES				1586314-3		VAL-U-LOK equivalent
<u>794577-</u> 1	YES				1586314-3		VAL-U-LOK equivalent

Part Number(s) being Modified:

	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>794577-1</u>	YES				1586314-3		VAL-U-LOK equivalent

Part Number(s) being Modified:

	(-)9						
Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>794577-</u> 1	YES				1586314-3		VAL-U-LOK equivalent