



Product Termination Notification



Product Group: Vishay Ceramic Capacitors / March 23, 2020 / PTN-CC-002-2020 Rev 0

Discontinuation of a few leaded MLCC part numbers

DESCRIPTION OF CHANGE: Due to discontinuation of the chip inserts (see PTN-MLC-00003-2019 and PTN-MLC-00004-2019) we need to discontinue a few part numbers out of our leaded MLCC Series.

CLASSIFICATION OF CHANGE: Product Termination

REASON FOR CHANGE: Chip inserts discontinued

EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE: N/A

PRODUCT CATEGORY: Ceramic Capacitors

PART NUMBERS/SERIES/FAMILIES AFFECTED: see attached list

VISHAY BRAND(s): Vishay BCcomponents

TIME SCHEDULE:

Last Time Buy Date: N/A

Last Time Shipment Date: N/A

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: By part number

QUALIFICATION DATA: N/A

This PTN is considered approved, without further notification, unless we receive specific customer concerns before June 23, 2020 or as specified by contract.

ISSUED BY: Product Marketing Ceramic Capacitors

Florian Weyland, Manager Product Marketing Ceramic Capacitors, E-mail: florian.veyland@vishay.com

For further information, please contact your regional Vishay office.

The Americas

Mark Walsh
Vishay Intertechnology, Inc.
15 Daigle Lane, Suite 103
Sanford, ME 04073 USA
Phone: +1-207-490-7206
Fax: +1-207-490-7213
mark.walsh@vishay.com

Europe

Martin Leupold
Vishay Electronic GmbH
Dr.-Felix-Zandman-Platz 1
D-95100 Selb
Phone : +49-9287-71-2535
Fax: +49-9287-71-2675
martin.leupold@vishay.com

Asia/Pacific

Boonhooi Tan
Vishay Asia Pte Ltd.
37A Tampines St. 92 #07-00
Singapore 528886
Phone : +65-6780-7759
Fax : +65-6780-7749
boonhooi.tan@vishay.com

Vishay Intertechnology, Inc.

Corporate Headquarters: 63 Lancaster Avenue, Malvern, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657

www.vishay.com

ONE OF THE WORLD'S LARGEST MANUFACTURERS OF DISCRETE SEMICONDUCTORS AND PASSIVE COMPONENTS



Product Termination Notification



Product Group: Vishay Ceramic Capacitors / March 23, 2020 / PTN-CC-002-2020 Rev 0

Part numbers affected:

Vishay PN	Chip insert (Vitramon PN)	Chip insert (Vitramon PTN No)
A473#15X7RF5###V	VJ0805Y473KXABB31	PTN-MLC-00003-2019
K473#15X7RF5###V		
A563#15X7RF5###V	VJ0805Y563KXABB31	PTN-MLC-00003-2019
K563#15X7RF5###V		
A473#15X7RH5###V	VJ0805Y473KXBBB31	PTN-MLC-00003-2019
K473#15X7RH5###V		
A103#20C0GF5###V	VJ1206A103JXABB31	PTN-MLC-00003-2019
K103#20C0GF5###V		
A103#20C0GH5###V	VJ1206A103JXBBB31	PTN-MLC-00003-2019
K103#20C0GH5###V		
A103#20C0GF5###R	VJ1206A103JXABB31X	PTN-MLC-00004-2019
K103#20C0GF5###R		
K103#20C0GF5###H		
A103#20C0GH5###R	VJ1206A103JXBBB31X	PTN-MLC-00004-2019
K103#20C0GH5###R		
K103#20C0GH5###H		

End of list