

Global Change Notification (GCN)

Product Family	Premo-Flex	10636399	
Troduct runniy	Tremo flex		
		GCN Number	
Series	15266, 15267, 15268	May 13, 2014	
		Date Issued	
Reason For Change	Change Construction Or Material		
Change Description	This letter is to inform you about some changes in the Premo-Flex Series assemblies. We are implementing a continuous insulation between the conductors and backer. The assemblies will be manufactured with the same materials and same end thickness of 0.30mm, but different construction and be different in appearance. These changes have been qualified by Molex.		
		After	
Before			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.		
Reason For Short Notice Exception	Special Request		
Assessment Of Change (How Product Will Be Qualified & Validated)	Product change has been qualified		
Internal Molex Qualification Date (Planned Date Information Available)	April 30, 2014		
Sample Availability Date (Changed Part)	April 30, 2014		
Date of Implementation	July 01, 2014		
Method of Identifying Change	Running change to part numbers		
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com