

Product/Process Change Notification PCN08172

Product:	Micropax™ Connectors		Part Numbers Concerned:	See list attached
Product Manager:	Jorge Ramirez		Issue Date:	19 Nov, 2008
			Page(s):	1/1
Distribution:	GLOBAL			

Subject:

Micropax™ Connectors; Inner-colour Change Only THIS IS NOT A DISCONTINUANCE NOTICE

Nature of Change:

Micropax connectors have metal outer shells. Colour of plastic inner-housing for all connectors will change from "black" to "natural."

Impact of change:

None. Resin will remain the same. Only the colour will change. These connectors are internal board-to-board connectors; Colour is not normally a customer requirement. Older black connectors mate with newer natural connectors.

Reason for change:

This change will consolidate resins and support increased responsiveness to customers. Manufacturing lead time for promoted Micropax™ part numbers is normally two weeks.

Implementation Date:

After January 15, 2009

Affected Part Numbers:

See attached list

For questions regarding this PCN contact:

Jorge Alberto Ramirez Product Specialist

E-Mail: jorge.a.ramirez@fci.com

Or contact your nearest FCI representative

E-3519 GS-23-018