

# PRODUCT CHANGE NOTIFICATION

Product Category FIBER DISTRIBUTION 20200610-01

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 20200610

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

We transitioned from Phosphor Bronze to Zirconia split sleeves on FADSLCAQ-L parts.

Photos/Drawing (where applicable)

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2020	6	15

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Type	Replacement Part
FADSLCAQ-L	Direct Replacement	FADSLCZAQ-L