

<b>PCN Number:</b>	20150626000	<b>PCN Date:</b>	07/06/2015
--------------------	-------------	------------------	------------

<b>Title:</b>	Datasheet update for DS92LV2411/DS92LV2412		
---------------	--	--	--

<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
--------------------------	-----------------------------	--------------	------------------

<b>Change Type:</b>			
---------------------	--	--	--

<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design	<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet	<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change	<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site	<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process	<input type="checkbox"/>	Wafer Fab Materials
				<input type="checkbox"/>	Wafer Fab Process

### PCN Details

**Description of Change:**

Texas Instruments Incorporated is announcing an information only notification.

The product datasheet(s) is updated as seen in the change revision history below:



**DS92LV2411, DS92LV2412**  
 SNLS302E – MAY 2010 – REVISED FEBRUARY 2015 [www.ti.com](http://www.ti.com)

Changes from Revision D (April 2014) to Revision E	Page
• Changed "Terminal" terminology back to "Pin" .....	1
• Added statement about checkerboard pattern from deserializer data output when in BIST mode .....	32
• Added note that BISTEN pin must be high and REG = 0 to use BIST mode. ....	32
• Changed deserializer Reg 0x02[6] definition to match correct OSS_SEL behavior .....	38

The datasheet number will be changing.

Device Family	Change From:	Change To:
<a href="#">DS92LV2411/DS92LV2412</a>	SNLS302D	<b>SNLS302E</b>

These changes may be reviewed at the datasheet links provided.  
<http://www.ti.com/product/ds92lv2411>

**Reason for Change:**

To more accurately reflect device characteristics.

**Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):**

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

**Changes to product identification resulting from this PCN:**

None.

**Product Affected:**

DS92LV2411SQ/NOPB	DS92LV2411SQX/NOPB	DS92LV2412SQE/NOPB
DS92LV2411SQE/NOPB	DS92LV2412SQ/NOPB	DS92LV2412SQX/NOPB

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>