

Product Change Notice

PCN#: EE-PCN17035

07/21/2017

CLASSIFICATION OF CHANGE:

End of Life.

DESCRIPTION OF CHANGE:

Discontinuance of product supply.

REASON FOR CHANGE:

The UP2SC family product has reached end of life..

There is no direct replacement. The DR1040 family is recommended as a potential replacement option.

PARTS FAMILIES AFFECTED:

Please see list on page 2.

SAMPLE AVAILABILITY:

N/A

QUALIFICATION DATA:

N/A

ISSUED BY:

Global Product Manager: Steve Subiry

CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).

PARTS LIST
UP2SC-100-R
UP2SC-101-R
UP2SC-120-R
UP2SC-121-R
UP2SC-150-R
UP2SC-151-R
UP2SC-180-R
UP2SC-181-R
UP2SC-1R0-R
UP2SC-1R5-R
UP2SC-220-R
UP2SC-221-R
UP2SC-270-R
UP2SC-271-R
UP2SC-2R2-R
UP2SC-330-R
UP2SC-331-R
UP2SC-390-R
UP2SC-391-R
UP2SC-3R0-R
UP2SC-470-R
UP2SC-4R7-R
UP2SC-560-R
UP2SC-680-R
UP2SC-6R8-R
UP2SC-820-R