

TE Connectivity

Product Change Notification: E-18-014492 PCN Date: 19-SEP-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
RECEPTACLE, FASTON, FLAG, .250 SERIES

Description of Changes
Add Nickel under plating for 2232111-1 The plated specification change from Tin plating only to Tin over Nickel plating

Reason for Changes:

Product Improvement. There have been customer complaints on 2232111-1 due to oxidation of Tin plated contacts during storage/ transit. Even though this is not affecting product performance, to better serve our customers, TE connectivity will supply Tin plated over Nickel version

Estimated Dates:

Last Order Date (Obsolete Parts Only):

Pirst Date To Ship (Changed Parts Only):

28-SEP-2018

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2232111-1	NO	. 0					

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
2232111-1	NO						

Part Number(s) being Modified:

	Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
	Imber	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
2232	111-1	NO						