

TE Connectivity

Product Change Notification: E-14-012088

PCN Date: 20-AUG-14

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: Various pins and sockets used on Arinc 404 that are mounted

Description of Changes Obsoleting only those dash numbers where contacts are mounted on tape. All other dash numbers or part numbers are not effected. There are no changes to p/n 205117-1 except for a Rev. change to drawing.

Reason for Changes:				
Discontinuance. No sales for these contacts that are mounted on tape.				
Estimated Dates:				
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):			
	29-AUG-2014			
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):			
	No Mixed Shipments			

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number(s)	Number	Number(s)	Difference
205117-1	NO					

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Current Revisior	New Revisior
205117	L	