


Light is OSRAM

Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048)
OS-PDN-2021-015

16 February 2021

Last order: 31 March 2021
Last delivery: 30 May 2021



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
GW TBLZH1.EM-JA7-24S5-0-20-T06-XX	Q65112A8590	DURIS F	Discontuniation of MMP Device	No replacement		
GW TBLZH2.EM-JA8-2200-1-40-T06	Q65112A9076	DURIS F	Discontuniation of MMP Device	No replacement		
GW TBLZH3.EM-JA9-2200-1-20-T06	Q65112A9077	DURIS F	Discontuniation of MMP Device	No replacement		
GW TBLZH1.EM-JA7-24S5-0-20-T06-W	Q65112A9256	DURIS F	Discontuniation of MMP Device	No replacement		
GW TBLZH1.EM-JB5-22S5-20-T06-XX	Q65113A0051	DURIS F	Discontuniation of MMP Device	No replacement		
GWM TBLZH4.EM-LA6-2240-GB-T01-IT	Q65113A0167	DURIS F	Discontuniation of MMP Device	No replacement		
GWM TBLZH4.EM-PA1-2765-GA-T01-IT	Q65113A0168	DURIS F	Discontuniation of MMP Device	No replacement		
GWM TBLZH5.EM-JA7-2200-GC-T01-IT	Q65113A0314	DURIS F	Discontuniation of MMP Device	No replacement		
GWM T4DWF1.EM-FC1-2710-1-T02-IT	Q65113A0695	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T4DWF1.EM-FC2-4940-1-T01-IT	Q65113A0696	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T4DWF1.EM-FC2-4940-1-T02-IT	Q65113A0697	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T6D2F1.EM-LA8-5000-1-T01-IT	Q65113A0698	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T6D2F1.EM-LA8-5000-1-T02-IT	Q65113A0699	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T6D2F1.EM-LA7-2700-1-T01-IT	Q65113A0700	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T6D2F1.EM-LA7-2700-1-T02-IT	Q65113A0701	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T6D2F1.EM-LA7-3000-1-T01-IT	Q65113A0702	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T6D2F1.EM-LA7-3000-1-T02-IT	Q65113A0703	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T6D2F1.EM-LA9-4000-1-T02-IT	Q65113A0704	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T6D2F1.EM-LA9-4000-1-T01-IT	Q65113A0705	DURIS L	Discontuniation of MMP Device	No replacement		
GWM T4DWF1.EM-FC1-2710-1-T01-IT	Q65113A0706	DURIS L	Discontuniation of MMP Device	No replacement		
GWM JCLPS2.EM-GVH1-2200-1-R33-LDS	Q65113A0808	DURIS E5050	Discontuniation of MMP Device	No replacement		
GWM JCLPS2.EM-GWH3-2700-1-R33-LDS	Q65113A0809	DURIS E5050	Discontuniation of MMP Device	No replacement		
GWM JCLPS2.EM-GWH4-3000-1-R33-LDS	Q65113A0810	DURIS E5050	Discontuniation of MMP Device	No replacement		
GWM JCLPS2.EM-GWH5-3500-1-R33-LDS	Q65113A0811	DURIS E5050	Discontuniation of MMP Device	No replacement		
GWM JCLPS2.EM-H2H5-4000-1-R33-LDS	Q65113A0812	DURIS E5050	Discontuniation of MMP Device	No replacement		

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
GWM JCLPS2.EM-H2H5-5000-1-R33-LDS	Q65113A0813	DURIS E5050	Discontinuation of MMP Device	No replacement		
GWM JCLPS2.EM-H2H5-6500-1-R33-LDS	Q65113A0814	DURIS E5050	Discontinuation of MMP Device	No replacement		
GWM T4DSF1.EM-CA6-5700-1-T02	Q65113A0869	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T4DSF1.EM-CA6-5700-1-T01	Q65113A0870	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T4DSF1.EM-CA5-2850-1-T02	Q65113A0871	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T4DSF1.EM-CA5-2850-1-T01	Q65113A0872	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T4DTF1.EM-CA9-5350-1-T01-LDS	Q65113A0927	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T4DTF1.EM-CA5-5000-1-T01-LDS	Q65113A0928	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T4DTF1.EM-CA7-2700-1-T01-LDS	Q65113A0929	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T4DTF1.EM-CA8-2800-1-T01-LDS	Q65113A0930	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T6D4F1.EM-PA4-3000-1-T01-LDS	Q65113A1077	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T6D4F1.EM-PA6-5000-1-T01-LDS	Q65113A1078	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T6D4F1.EM-PA5-4150-1-T01-LDS	Q65113A1079	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T6D4F1.EM-PA3-2800-1-T01-LDS	Q65113A1080	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T5DWF1.EM-FC7-27S5-1-T01-LDS	Q65113A1347	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T5DWF1.EM-FC7-27S5-1-T02-LDS	Q65113A1348	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T5DWF1.EM-FC5-28S5-1-T01-LDS	Q65113A1349	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T5DWF1.EM-FC5-28S5-1-T02-LDS	Q65113A1350	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T5DWF1.EM-FC9-3150S5-1-T01-LDS	Q65113A1351	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T5DWF1.EM-FC9-3150S5-1-T02-LDS	Q65113A1352	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T5DWF1.EM-FC8-4150S5-1-T01-LDS	Q65113A1353	DURIS L	Discontinuation of MMP Device	No replacement		
GWM T5DWF1.EM-FC8-4150S5-1-T02-LDS	Q65113A1354	DURIS L	Discontinuation of MMP Device	No replacement		
GWM P9L1SA.EM-L1-22R5+K1-65R5-1-12.5-R33	Q65113A1471	DURIS E5050	Discontinuation of MMP Device	No replacement		
GWM P9L9SA.EM-L1-22R5+K1-65R5-1-17-R33	Q65113A1472	DURIS E5050	Discontinuation of MMP Device	No replacement		

Device	Product Descr.	Ordering Code	Repl.	Product Descr.
GW TBLZH1.EM	GW TBLZH1.EM-JA7-24S5-0-20-T06-XX	Q65112A8590	none	
GW TBLZH2.EM	GW TBLZH2.EM-JA8-2200-1-40-T06	Q65112A9076	none	
GWM TBLZH3.EM	GW TBLZH3.EM-JA9-2200-1-20-T06	Q65112A9077	none	
GW TBLZH1.EM	GW TBLZH1.EM-JA7-24S5-0-20-T06-W	Q65112A9256	none	
GW TBLZH1.EM	GW TBLZH1.EM-JB5-22S5-20-T06-XX	Q65113A0051	none	
GWM TBLZH4.EM	GWM TBLZH4.EM-LA6-2240-GB-T01-IT	Q65113A0167	none	
GWM TBLZH4.EM	GWM TBLZH4.EM-PA1-2765-GA-T01-IT	Q65113A0168	none	
GWM TBLZH5.EM	GWM TBLZH5.EM-JA7-2200-GC-T01-IT	Q65113A0314	none	
GWM T4DWF1.EM	GWM T4DWF1.EM-FC1-2710-1-T02-IT	Q65113A0695	none	
GWM T4DWF1.EM	GWM T4DWF1.EM-FC2-4940-1-T01-IT	Q65113A0696	none	
GWM T4DWF1.EM	GWM T4DWF1.EM-FC2-4940-1-T02-IT	Q65113A0697	none	
GWM T6D2F1.EM	GWM T6D2F1.EM-LA8-5000-1-T01-IT	Q65113A0698	none	
GWM T6D2F1.EM	GWM T6D2F1.EM-LA8-5000-1-T02-IT	Q65113A0699	none	
GWM T6D2F1.EM	GWM T6D2F1.EM-LA7-2700-1-T01-IT	Q65113A0700	none	
GWM T6D2F1.EM	GWM T6D2F1.EM-LA7-2700-1-T02-IT	Q65113A0701	none	
GWM T6D2F1.EM	GWM T6D2F1.EM-LA7-3000-1-T01-IT	Q65113A0702	none	
GWM T6D2F1.EM	GWM T6D2F1.EM-LA7-3000-1-T02-IT	Q65113A0703	none	
GWM T6D2F1.EM	GWM T6D2F1.EM-LA9-4000-1-T02-IT	Q65113A0704	none	
GWM T6D2F1.EM	GWM T6D2F1.EM-LA9-4000-1-T01-IT	Q65113A0705	none	
GWM T4DWF1.EM	GWM T4DWF1.EM-FC1-2710-1-T01-IT	Q65113A0706	none	
GWM JCLPS2.EM	GWM JCLPS2.EM-GVH1-2200-1-R33-LDS	Q65113A0808	none	
GWM JCLPS2.EM	GWM JCLPS2.EM-GWH3-2700-1-R33-LDS	Q65113A0809	none	
GWM JCLPS2.EM	GWM JCLPS2.EM-GWH4-3000-1-R33-LDS	Q65113A0810	none	
GWM JCLPS2.EM	GWM JCLPS2.EM-GWH5-3500-1-R33-LDS	Q65113A0811	none	
GWM JCLPS2.EM	GWM JCLPS2.EM-H2H5-4000-1-R33-LDS	Q65113A0812	none	
GWM JCLPS2.EM	GWM JCLPS2.EM-H2H5-5000-1-R33-LDS	Q65113A0813	none	
GWM JCLPS2.EM	GWM JCLPS2.EM-H2H5-6500-1-R33-LDS	Q65113A0814	none	
GWM T4DSF1.EM	GWM T4DSF1.EM-CA6-5700-1-T02	Q65113A0869	none	
GWM T4DSF1.EM	GWM T4DSF1.EM-CA6-5700-1-T01	Q65113A0870	none	
GWM T4DSF1.EM	GWM T4DSF1.EM-CA5-2850-1-T02	Q65113A0871	none	
GWM T4DSF1.EM	GWM T4DSF1.EM-CA5-2850-1-T01	Q65113A0872	none	
GWM T4DTF1.EM	GWM T4DTF1.EM-CA9-5350-1-T01-LDS	Q65113A0927	none	
GWM T4DTF1.EM	GWM T4DTF1.EM-CA5-5000-1-T01-LDS	Q65113A0928	none	
GWM T4DTF1.EM	GWM T4DTF1.EM-CA7-2700-1-T01-LDS	Q65113A0929	none	
GWM T4DTF1.EM	GWM T4DTF1.EM-CA8-2800-1-T01-LDS	Q65113A0930	none	
GWM T6D4F1.EM	GWM T6D4F1.EM-PA4-3000-1-T01-LDS	Q65113A1077	none	
GWM T6D4F1.EM	GWM T6D4F1.EM-PA6-5000-1-T01-LDS	Q65113A1078	none	
GWM T6D4F1.EM	GWM T6D4F1.EM-PA5-4150-1-T01-LDS	Q65113A1079	none	
GWM T6D4F1.EM	GWM T6D4F1.EM-PA3-2800-1-T01-LDS	Q65113A1080	none	
GWM T5DWF1.EM	GWM T5DWF1.EM-FC7-27S5-1-T01-LDS	Q65113A1347	none	
GWM T5DWF1.EM	GWM T5DWF1.EM-FC7-27S5-1-T02-LDS	Q65113A1348	none	
GWM T5DWF1.EM	GWM T5DWF1.EM-FC5-28S5-1-T01-LDS	Q65113A1349	none	
GWM T5DWF1.EM	GWM T5DWF1.EM-FC5-28S5-1-T02-LDS	Q65113A1350	none	
GWM T5DWF1.EM	GWM T5DWF1.EM-FC9-3150S5-1-T01-LDS	Q65113A1351	none	
GWM T5DWF1.EM	GWM T5DWF1.EM-FC9-3150S5-1-T02-LDS	Q65113A1352	none	
GWM T5DWF1.EM	GWM T5DWF1.EM-FC8-4150S5-1-T01-LDS	Q65113A1353	none	
GWM T5DWF1.EM	GWM T5DWF1.EM-FC8-4150S5-1-T02-LDS	Q65113A1354	none	
GWM P9L1SA.EM	GWM P9L1SA.EM-L1-22R5+K1-65R5-1-12.5-R33	Q65113A1471	none	
GWM P9L9SA.EM	GWM P9L9SA.EM-L1-22R5+K1-65R5-1-17-R33	Q65113A1472	none	
GWM P9L6SA.EM	GWM P9L6SA.EM-L2-22R5+K1K3-65R5-1-50-R33	Q65113A1473	none	