

2/27/2023

Subject: Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

Type (Only Checked Changes Apply	•)		
☐ Production/assembly location		aterial	☐ End of Life w/ replacement
☐ Part Number/Ordering Code		ckaging	☐ End of Life w/o replacement
		int of Purchase	☐ Additional tool/refurbishment
☐ Design (fit, form, function)	□ Pc	int of Pick up	☐ Cost/Lead Time
☐ Engineering record (non-fit, form, func	ction) \square Su	pply Chain	☐ Process
Additional Information			
From:		To:	
HT Order Code: 126-00244 HT Order Code: 156-00264			
Country of Origin: Milwaukee, WI		Country of Origin: Germany	
Production Location: Milwaukee, WI		Production Location: Germany	
Scope			
HT PN / Ordering Code Cu	Customer PN		Change Effective*
126-00244 12	26-00244	Immediate	
*FCC : 1: 1: 1: 1	9.1.95		

Reason for change: This change is based on a capacity restraint of 126-00244.

We ask that you please acknowledge this notification by 3/3/2023, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Amanda Harris

Quality Project Manager Office: 414 355 1130 x 8335 Email: <u>AHarris@htamericas.com</u>

^{*}Effective date is subject to change based on availability