

Discontinue MultiLINX Cable

XCN05010 (v1.1) May 3, 2005

Product Discontinuation Notice

Overview

Xilinx is discontinuing the MultiLINX download cable.

Product Affected

The MultiLINX download cable (ordering code HW-MULTILINX) is being discontinued. The <u>Platform Cable USB</u>, the <u>Parallel Cable IV</u>, and the <u>MultiPRO Desktop Tool</u> offer many of the same features and are alternatives to the MultiLINX cable.

Discontinued	os	Port	Configuration Mode	Alternative Product
Part Number	Platform			
HW-MULTILINX	PC	Parallel	JTAG	Parallel Cable IV (p/n HW-PC4) or
			(IEEE 1149.1)	MultiPRO (p/n HW-MULTIPRO)
	PC	Parallel	Slave Serial	Parallel Cable IV (p/n HW-PC4) or
				MultiPRO (p/n HW-MULTIPRO)
	PC	Parallel	SelectMAP	Parallel Cable IV (p/n HW-PC4) or
				MultiPRO (p/n HW-MULTIPRO)
	PC	USB	JTAG	Platform Cable USB (p/n HW-USB)
			(IEEE 1149.1)	
	PC	USB	Slave Serial	Platform Cable USB (p/n HW-USB)
	PC	USB	SelectMAP	Platform Cable USB (p/n HW-USB)
	PC/	RS-232	JTAG, Slave Serial,	None (use ISE 7.1i or earlier for
	Workstation		SelectMAP	iMPACT support and stock cables
				via the MultiLINX last time buy)

The <u>Platform Cable USB</u> introduced in December 2004 has a USB2.0 interface and is compatible with USB1.1. Assistance in planning for the replacement of the MultiLINX cable is available. Please contact your <u>Xilinx</u> <u>Sales Representative</u> for more information.

Description

Xilinx is discontinuing the MultiLINX cable; due to declining customer usage, it is no longer economically feasible to continue manufacturing the part. Xilinx has introduced the Platform Cable USB, the Parallel Cable IV, and the MultiPRO Desktop Tool as high-speed, cost-effective alternatives to the MultiLINX cable. Software support for the MultiLINX cable will be removed from the future ISE releases after the ISE7.1i and ISE 7.1i Service Pack releases in 2005.

Key Dates

Final orders will be accepted until September 26, 2005. Final deliveries must occur on or before October 3, 2005.

Response

Immediate response to this notification is not required.

© 2005 Xilinx, Inc. All rights reserved. All Xilinx trademarks, registered trademarks, patents, and disclaimers are as listed at http://www.xilinx.com/legal.htm.
All other trademarks and registered trademarks are the property of their respective owners. All specifications are subject to change without notice.

Important Notice: Since July 1, 2004, Xilinx Customer Notifications (PCN, PDN, and Quality Alerts) are being delivered via e-mail alerts sent by the MySupport website (http://www.xilinx.com/support). Register today and personalize your "MyAlerts" to include Customer Notifications. This change provides many benefits, including the ability to receive alerts for new and updated information about specific products, as well as alerts for other publications such as data sheets, errata, application notes, and so forth. For instructions on how to sign up, refer to Xilinx Answer Record 18683.

Revision History

The following table shows the revision history for this document.

Date	Version	Revision	
04/25/05	1.0	Initial release.	
05/03/05	1.1	Fix typographical error: change "MUTILINX" to "MULTILINX"	