

Date: 03/11/21

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Hardware

Products Affected

Part Number	Description	Old Revision	New Revision
SLC80081201G	SKU, ADVANCED CONSOLE MANAGER, SINGLE AC POWER SUPPLY, SLC8000 8- PORT, ROHS, TAA	K16	K17
SLC80081201S	SLC8000 8-PORT SINGLE AC POWER SUPPLY ADVANCED CONSOLE MANAGER, ROHS	K15	K16
SLC80161201G	SKU, ADVANCED CONSOLE MANAGER, SINGLE AC POWER SUPPLY, SLC8000 16- PORT, ROHS, TAA	K16	K17
SLC80161201S	SLC8000 16-PORT SINGLE AC POWER SUPPLY ADVANCED CONSOLE MANAGER, ROHS	K15	K16
SLC80161211S	SKU, ADVANCED CONSOLE MANAGER, RJ45 16-PORT, AC-SINGLE SUPPLY, SFP, SLC8000	G12	G13
SLC80162401G	SLC 8000 ADVANCED CONSOLE MANAGER, RJ45 16-PORT, DC-DUAL SUPPLY, TAA	G12	G13
SLC80162401S	SLC8000 16-PORT DUAL DC POWER SUPPLY ADVANCED CONSOLE MANAGER, ROHS	K14	K15
SLC80162411S	SLC8000 ADVANCED CONSOLE MANAGER, RJ45 16-PORT, DC-DUAL SUPPLY, SFP	G12	G13
SLC80321201G	SKU, ADVANCED CONSOLE MANAGER, SINGLE AC POWER SUPPLY, SLC8000 32- PORT, ROHS, TAA	K16	K17
SLC80321201S	SLC8000 32-PORT SINGLE AC POWER SUPPLY ADVANCED CONSOLE MANAGER, ROHS	K15	K16
SLC80322401G	SLC 8000 ADVANCED CONSOLE MANAGER, RJ45 32-PORT, DC-DUAL SUPPLY, TAA	G12	G13
SLC80322401S	SLC8000 32-PORT DUAL DC POWER SUPPLY ADVANCED CONSOLE MANAGER, ROHS	K14	K15
SLC80481201G	SKU, ADVANCED CONSOLE MANAGER, SINGLE AC POWER SUPPLY, SLC8000 48- PORT, ROHS, TAA	K16	K17
SLC80481201S	SLC8000 48-PORT SINGLE AC POWER SUPPLY ADVANCED CONSOLE MANAGER, ROHS	K15	K16
SLC80482401G	SKU, ADVANCE CONSOLE MANAGER, DUAL DC POWER SUPPLY, SLC8000 48-PORT, DUAL GIGE , TAA	G12	G13
SLC80482401S	SLC8000 48-PORT, ADVANCED CONSOLE MANAGER, DUAL DC, POWER SUPPLY, ROHS	K14	K15
SLC81161201S	SLC 8000 ADVANCED CONSOLE MANAGER, USB 16-PORT, SINGLE AC POWER SUPPLY, ROHS	J13	J14
SLC81161211S	SLC8000 ADVANCED CONSOLE MANAGER, USB 16-PORT, AC-SINGLE SUPPLY, SFP	G12	G13

7535 Irvine Center Drive | Suite 100 Irvine, CA 92618 USA



lantronix.com

SLC81162401S	SLC8000, ADVANCED CONSOLE MANAGER, USB 16-PORT, DUAL DC POWER	F12	F13
	SUPPLY, ROHS		
SLC81162411S	SLC8000 ADVANCED CONSOLE MANAGER, USB 16-PORT, DC-DUAL SUPPLY, SFP	G12	G13
SLC82321201S	SLC 8000 ADVANCED CONSOLE MANAGER, RJ45 16-PORT, USB 16-PORT, SINGLE	J14	J15
	AC POWER SUPPLY, ROHS		
FR1ACPS01	SINGLE INLET AC POWER SUPPLY	A11	A12
FR2DCPS01	DUAL INLET DC POWER SUPPLY	A11	A12

Description and Extent of Change

The SLC 8000 is changing its Single AC and Dual DC power supply tray to be mounted more securely. A new threaded hole on the tray is to prevent the power supply from falling out of the product when unplugging power cords.

Effect of Change on Fit, Form, or Function

Form change as noted above.

Effective Date of Change

This change will go into effect the listed products built from March 11, 2021 onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.

7535 Irvine Center Drive | Suite 100 Irvine, CA 92618 USA

☎ 800.526.8766
⊕ lantronix.com