

TENSILITY

Product Change Notification

June 24, 2016

PCN issue number: 00104

Product Type: Connector, dc plug


Change type: Manufacturing process and dimensional adjustment

Products affected by change:


Part Number	Part Description
50-00187	Connector, dc plug, 5.5x2.5xL20.5 mm, molding style, spring contacts

Product specification change: The revised specification illustrates the reduction of the outside diameter of the connector insulator from 6.5 ± 0.2 to 6.3 ± 0.3 mm.

Configuration change: The outside diameter of the connector insulator was reduced as a result of improving the molding process to eliminate potential flashing.



New Version



Old Version

Reason for change: To reduce instances of exposed flashing. Injection tooling was modified to alleviate the occurrence of flashing.

Anticipated impact on fit, form, function and reliability:

There will be no change to the fit or function of this product. The form will only be slightly affected by the modification of the insulator outside diameter. Connector mating will be unaffected. The reliability of the product will remain the same.

Please direct all questions regarding this PCN to:

engineering@tensility.com

541-323-3228