

Global Change Notification (GCN)

Product Family	Magnetic Jacks	10636537	
r roduce r drilly	5		
		GCN Number	
Series	85586, 85718, 85734, 85731, 85789, 85793, 85791, 85759, 85719, 85729	June 02, 2014	
		Date Issued	
Reason For Change	Tooling / Equipment Transfer		
Change Description	"The purpose of the change is the moving of the current production at contract manufacturer Audix. Audix are moving production to their main production facility 300m from No. 46 Xingnan Road, Jimei, Xiamen, Fujian, China to location No. 7 Rixin Road, Jimei, Xiamen, Fujian, China There is no change in processes, materials, equipments etc."		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-n	nail message.	
Reason For Short Notice Exception	Not Applicable		
Assessment Of Change (How Product Will Be Qualified & Validated)	there is no affect of fit, form or function		
Internal Molex Qualification Date (Planned Date Information Available)	May 09, 2014		
Sample Availability Date (Changed Part)	May 09, 2014		
Date of Implementation	June 30, 2014		
Method of Identifying Change	New Adress		
Recommended Replacement Parts	Not Applicable		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com