

PCN - 10 133

Issue Date: November 03 2010

| Product Name: | D-sub DP Series | | | | |
|----------------------------|--|-------------------------------------|------|--|--|
| | All PNs in DP Angled version | | | | |
| Product Manager: | Anup K.P. | | | | |
| Subject: | Product Change Notification | | | | |
| Distribution: | Global | | | | |
| Type of Change: | Manufacturing Process Change | | | | |
| Change Description: | Contact bending profile has been modified without changing the connector envelop, footprint or pitch. Previous Contact profile Modified Contact profile Connector envelop area is marked in Blue line | | | | |
| Reason for Change: | To introduce an alternate supplier to improve the lead time, and also to implement process standardisation and simplififcation. | | | | |
| Affected Parts: | See attached list. | | | | |
| Effective Date of Change: | December | 05 | 2010 | | |
| Last Time Buy Date: | N/A | N/A | N/A | | |
| Last Disty Return Date: | N/A | N/A | N/A | | |
| Datasheet Attached? | No | | | | |
| Qual/Test Data Attached? | No | | | | |
| Samples Availability Date: | October | 15 | 2010 | | |
| Available Alternatives? | No | | | | |
| Questions? | Contact your local FCI Representative, or | | | | |
| | Anup K.P. | | | | |
| | 00.91.484.66 | 00.91.484.6611582; anup.k-p@fci.com | | | |