

Announcing Limited Obsolescence of Select Potentiometers: No Last Time Buy Offer

Summary

As we continue to expand our Magnetic Sensor portfolio with new products, Honeywell Safety and Productivity Solutions (SPS) is also eliminating certain older product designs that have reached end of life. As such, SPS announcing an immediate obsolescence of select SS42 Magnetic Sensor IC's. The affected listings, based on lack of recent sales, are detailed in the list below.

This change is effective immediately and there will not be a last time buy opportunity.

Affected Listings

| SS421H |
|--------|
| SS421L |
| SS42R |

Action

Please inform any affected customers about this obsolescence.

Additional Materials

If distributors need to inform their customers about this obsolescence, a letter summarizing this announcement is available.

Contact Information

For additional information, please contact:

- Global Product Marketing Manager: James McKenna, <u>James.McKenna@honeywell.com</u>
- Product Marketing Specialist, NA Region: Ben Tollefson, <u>ben.tollefson@Honeywell.com</u>, +1 763-954-6254

December 15, 2016 © 2016 Honeywell International. All rights reserved.