



Product Change Notification (PCN)

PCN Number	503336	Date Issued	March 22, 2019
Reason for Change	Equipment Transfer, Production Transfer or Rearrangement		
Change Type Description	This letter is to inform you that production of the part(s) identified in this notice is being moved to a different production location. No changes will be made to the product as a result of this move.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date		
Internal Molex Qualification Date	September 20, 2019		
Sample Availability Date (Changed Part)	September 20, 2019		
Planned Implementation Date	September 30, 2019		
Method of Identifying Change	Factory order number		

Before Change

Impacted Products Pictures



After Change

Overview

- Molex Chengdu will add manufacture source to run the parts at the local qualified molding vendors, qualify molds and able to run the production in both locations Molex Chengdu & local qualified molding vendors under the same condition which means the same raw material from the same source, the same process and the same quality control plan. And the vendor only produce components. All finished parts are assembled in Molex plant .
- Molex Chengdu engineers team will follow very closely because we will manage our external vendor like an extension of Molex Chengdu and with the same process and quality management. Team will audit/manage the vendor and their manufacture process.
- Product Impact
No impact to fit, form or function
- Part Number Impact
Please see the attachment
- Qualification Reports and samples available upon request after the date shown above

DEFERRED



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:503336**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

334720601

334720602

334720606

334720607

334720701

334820401

334820601

334820602

334822101

334822102

334823601

334823602

334824001

334828601

340620025

340620026

340620027

340620028

340624008

340624009

346750002

346750004

347520204

349851601

349861601

349861602

Part numbers affected:

33472-0602
33472-0603
33472-0606
33482-0401
33482-1601
33482-2102
34062-4008
34675-0001
34985-1601
34985-1606
34985-2080
34985-2177
34985-2183
34985-4003
160073-3112