



## Product Change Notification / ASER-13JLHX847

---

### Date:

17-May-2022

### Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

### PCN Type:

Manufacturing Change

### Notification Subject:

CCB 5140 Final Notice: Implement top marking changes for PIC24FJ64GP202-E/SO, PIC24FJ32GP202-E/SO, PIC24FJ64GP202-I/SO, PIC24FJ32GP202-I/SO, PIC24FJ64GP202T-I/SO and PIC24FJ32GP202T-I/SO catalog part numbers (CPN) available in 28L SOIC (.300in) package assembled at MTAI assembly site.

### Affected CPNs:

[ASER-13JLHX847\\_Affected\\_CPN\\_05172022.pdf](#)

[ASER-13JLHX847\\_Affected\\_CPN\\_05172022.csv](#)

### Notification Text:

**PCN Status:**Final Notification

**PCN Type:**Manufacturing Change

**Microchip Parts Affected:**Please open one of the files found in the Affected CPNs section.

Note: For your convenience Microchip includes identical files in two formats (.pdf and .xls)

**Description of Change:**Implement top marking changes for PIC24FJ64GP202-E/SO, PIC24FJ32GP202-E/SO, PIC24FJ64GP202-I/SO, PIC24FJ32GP202-I/SO, PIC24FJ64GP202T-I/SO and PIC24FJ32GP202T-I/SO catalog part numbers (CPN) available in 28L SOIC (.300in) package assembled at MTAI assembly site.

### Pre and Post Change Summary:

	Pre Change	Post Change
Marking Line #1	PIC24FJ64GU202	PIC24FJ64GP202
	PIC24FJ32GU202	PIC24FJ32GP202
	PIC24FJ64GU202	PIC24FJ64GP202
	PIC24FJ32GU202	PIC24FJ32GP202
	PIC24FJ64GU202	PIC24FJ64GP202
	PIC24FJ32GU202	PIC24FJ32GP202

**Impacts to Data Sheet:**None

**Change Impact:**None

**Reason for Change:**To improve productivity by implementing top marking changes.

**Change Implementation Status:**In Progress

**Estimated First Ship Date:**June 22, 2022 (date code: 2226)

Note: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

**Time Table Summary:**

	May 2022					June 2022			
Workweek	1 9	2 0	2 1	2 2	2 3	2 4	2 5	2 6	2 7
Final PCN Issue Date			x						
Estimated Implementation Date							x		

**Method to Identify Change:**Traceability code, Top marking

**Qualification Report:**Not Applicable

**Revision History:**May 17, 2022: Issued final notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the

material content of the applicable products.

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

---

ASER-13JLHX847 - CCB 5140 Final Notice: Implement top marking changes for PIC24FJ64GP202-E/SO, PIC24FJ32GP202-E/SO, PIC24FJ64GP202-I/SO, PIC24FJ32GP202-I/SO, PIC24FJ64GP202T-I/SO and PIC24FJ32GP202T-I/SO catalog part numbers (CPN) available in 28L SOIC (.300in) package assembled at MTAI assembly site.

---

Affected Catalog Part Numbers (CPN)

PIC24FJ64GP202-E/SO

PIC24FJ32GP202-E/SO

PIC24FJ64GP202-I/SO

PIC24FJ32GP202-I/SO

PIC24FJ64GP202T-I/SO

PIC24FJ32GP202T-I/SO