

Honeywell Aerospace 12001 State Highway 55 Plymouth, MN 55441

October 29, 2021

Subject: Notice of End of Life for HMC1051ZL Magnectic Sensor

Dear Valued Honeywell Customer:

Honeywell regrets to announce the discontinuance of the HMC1051ZL magnetic sensor, due to supply chain challenges. Honeywell will not be able to support any futher orders for this part.

For any technical support, customers may reach out to PlymouthSupport@Honeywell.com.

If you require further information regarding this notice, please contact Customer Business Manager, Kim Olson at Kim.Olson@Honeywell.com.

We value your feedback, and would be happy to discuss any related issues. Thank you for your consideration.

Best Regards,

Jeevish G Gurumoorthi
Honeywell Aerospace
Offering Manager (Navigation & Sensors)
Magnetic Sensors - Product Lead
JeevishGlastine.Gurumoorthi@Honeywell.com