

Product Change Notification

TE Connectivity

Product Change Notification: P-16-013976 PCN Date: 20-DEC-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing Location Change of Menlo Park Appliances Tubing ES2000 Products

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from Menlo Park to Shanghai. This Product Notification is to inform our customers that TE Connectivity (TE) will also be moving the manufacturing of ES2000 products to the Shanghai tubing facility in China. The Shanghai facility is an already established Heat Shrinkable Tubing (Tubing or Products) manufacturing site. - since 1996.

Other attachments:

ES2000 PCN Information

ES2000 Affected Part Numbers & Packaging details

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. Upon request, a PPAP Level 2 will be available. This notification is to inform our customers that TE Connectivity is closing our Menlo Park facility in USA and moving the production to our Shanghai facility in China. The receiving facility is already an established Heat Shrinkable Tubing (Tubing or Products) manufacturing site - since 1996. See attached document.

Estimated	

Estimated bates.	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	21-MAR-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	21-MAR-2019

Part Number(s) being Modified:

Part Number	Part Discontinued	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P017	per PCN NO	Drawing		"5-1190481-7", "ES2000-NO.2-B9 0-40MM"		Fait Number(s)	Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9- 0-STK", "ES2000-2-4FOOT"			
121397P018	NO			"3-1190883-8", "ES2000-NO.3-B8- 0-50MM"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8- 0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7- 0-STK"			
<u>829131P02</u> 1	NO			"7-1196474-9", "ES2000-NO.1-C1 0-STK"	-		
829131P026	NO			"8-1196474-3", "ES2000-NO.1-C1 0-25MM"	-		

Part Number(s) being Modified:

i di titaliboi(d) boing woulder.						
Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Fait Nulliber(s)	Number	Part Number(s)	Difference
062725004	NO			"5-1190481-7", "ES2000-NO.2-B9-			
063725P017	NO			0-40MM"			
063725P02	2 NO			"6-1190481-1", "ES2000-NO.2-B9-			
003723102	INO			0-STK", "ES2000-2-4FOOT"			

Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Fait Nulliber(s)	Number	Part Number(s)	Difference
121397P018	NO			'3-1190883-8", "ES2000-NO.3-B8-			
				0-50MM"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8- 0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7- 0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1- 0-STK"			
829131P026	NO NO			"8-1196474-3", "ES2000-NO.1-C1- 0-25MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P017				"5-1190481-7", "ES2000-NO.2-B9- 0-40MM"		- art (am. 201(c)	2
063725P022	NO NO			"6-1190481-1", "ES2000-NO.2-B9- 0-STK", "ES2000-2-4FOOT"			
121397P018	NO NO			"3-1190883-8", "ES2000-NO.3-B8- 0-50MM"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8- 0-STK"			
130599P006	NO NO			"6-1190948-4", "ES2000-NO.4-B7- 0-STK"			
829131P02	NO			"7-1196474-9", "ES2000-NO.1-C1- 0-STK"			
829131P026	NO NO			"8-1196474-3", "ES2000-NO.1-C1- 0-25MM"			

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Fait Nulliber(s)	Number	Part Number(s)	Difference
063725P022	NO NO			"6-1190481-1", "ES2000-NO.2-B9- 0-STK", "ES2000-2-4F0OT"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8- 0-STK"			
130599P006	NO NO			"6-1190948-4", "ES2000-NO.4-B7- 0-STK"			
829131P02 ⁻	NO			"7-1196474-9", "ES2000-NO.1-C1- 0-STK"			

Part Number(s) being Modified:

	, semig meamea.						
Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Fait Number(s)	Number	Part Number(s)	Difference
063725P022	NO NO			"6-1190481-1", "ES2000-NO.2-B9-			
003723F022	. INO			0-STK", "ES2000-2-4FOOT"			
121397P024	NO NO			'4-1190883-3", "ES2000-NO.3-B8-			
1213977024	NO			0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-			
1305997000) NO			0-STK"			
829131P021	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substib.lte Part Number	Substitute Alias Part Number(s)	Description Of Difference
				'7-1196474-9", "ES2000-NO.1-ClSTK"			