

PRODUCT CHANGE NOTIFICATION

Product Category CABINETS AND THERMALS 20221010-1

Product Group CONVERGED INFRASTRUCTURE

ISSUE DATE: 10-Oct-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

In an effort to transition FlexFusion™ as the primary cabinet offering, we are further reducing the available Net-Access N-Type cabinet part numbers and discontinuing all remaining S-Type cabinet part numbers. Comparable FlexFusion™ cabinet provided.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	10	17
Old product discontinuation date*	2022	12	30

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerService@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA FORM C2-1003 DATE: 06APR21 APPR: MURILLO	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

IMPACTED PART NUMBER(s) Replacement Part 1

DHLKB/N	NO-REPLACEMENT
DN8212B-004/N	NO-REPLACEMENT
DNE6822WVBP/N	NO-REPLACEMENT
DNE6829WVBP/N	NO-REPLACEMENT
DNE8822W/N	NO-REPLACEMENT
DNE8829W/N	NO-REPLACEMENT
E6212B1FP	E6212B1
N8121WSPEBDIS/N	XG85121WS00Q5
N8122WSPEBDIS/N	XG85121WS00Q5
N8212BC	N8212B
N8222BC	N8222B
N8222BE	N8222B
N8222BX00114	NO-REPLACEMENT
N8222WC	N8222B
N8229BU	N8222B
N8229WCLSE3/N	NO-REPLACEMENT
N8229WTCLSE3/N	NO-REPLACEMENT
N8512BE	N8512B
N8512BX00103	N8512B
N8519B	N8512B
N8522BC	N8522B
N8522BE	N8522B
N8522BX00009	NO-REPLACEMENT
N8522BX00152	N8522B
N8522WX00009	NO-REPLACEMENT
N8529BC	N8522B
N8529BSE	NO-REPLACEMENT
N8529GEVTCB/N	NO-REPLACEMENT
N8529WCLSE3/N	NO-REPLACEMENT
N8529WSE	NO-REPLACEMENT
N8822B	N8812B
N8822BC	N8812B
N8822BX00109	NO-REPLACEMENT
N8829B	N8812B
N8829BC	N8812B
N8829BX00079	N8812B
N8829W	N8822WC
N8869BCTB/N	NO-REPLACEMENT
S12822WMOR/N	NO-REPLACEMENT
S6212BU	XG64212BS002P
S6222BU	XG64222BS002P
S6222BX00202	NO-REPLACEMENT
S6222WAU-001/N	NO-REPLACEMENT
S6222WP-004/N	NO-REPLACEMENT
S6222WPSP-002/N	NO-REPLACEMENT

S6222WPSP-004/N	NO-REPLACEMENT
S6222WX00009	NO-REPLACEMENT
S6229WALSE3/N	NO-REPLACEMENT
S6229WATLSE3/N	NO-REPLACEMENT
S6529WALSE3/N	NO-REPLACEMENT
S6822B	XG64822BS0001
S6822BX00113	NO-REPLACEMENT
S6822WX00094	NO-REPLACEMENT
S6829WALSE3/N	NO-REPLACEMENT
S7112WAAP-001	NO-REPLACEMENT
S7112WUDBN/N	NO-REPLACEMENT
S7122WSPXC001/N	XG75121WS00FQ
S7122WUDBN/N	NO-REPLACEMENT
S7123WUDBS5/N	NO-REPLACEMENT
S7212WUDBN/N	NO-REPLACEMENT
S7222RUIISO/N	NO-REPLACEMENT
S7222WUDBN/N	NO-REPLACEMENT
S7229WALSE3/N	NO-REPLACEMENT
S7229WATLSE3/N	NO-REPLACEMENT
S7512BAAP-002	NO-REPLACEMENT
S7512WU-076/N	NO-REPLACEMENT
S7522B	XG74522BS0001
S7522BX00124	NO-REPLACEMENT
S7522WUDBN/N	NO-REPLACEMENT
S7522WX00051	NO-REPLACEMENT
S7522WX00058	XG74522WS002P
S7812WUDBN/N	NO-REPLACEMENT
S7819WALSE3/N	NO-REPLACEMENT
S7822WA-079/N	NO-REPLACEMENT
S7822WA-080/N	NO-REPLACEMENT
S7822WUDBN/N	NO-REPLACEMENT
S7822WUSBK/N	NO-REPLACEMENT
S7822WX00038	XG74822WS002P
S7822WX00053	NO-REPLACEMENT
S7829WALSE3/N	NO-REPLACEMENT
S7829WALSE4/N	NO-REPLACEMENT
S7829WALSE6/N	NO-REPLACEMENT
S7829WALSE7/N	NO-REPLACEMENT
S7829WALSE9/N	NO-REPLACEMENT
S7829WATLSE4/N	NO-REPLACEMENT
S8129WALSE3/N	NO-REPLACEMENT
S8212BU	XG84212BS002P
S8222BAEP/N	NO-REPLACEMENT
S8222BAEP01/N	NO-REPLACEMENT
S8222BU	XG84222BS002P
S8222RUIISO/N	NO-REPLACEMENT
S8222WUIISO/N	NO-REPLACEMENT
S8229WALSE3/N	NO-REPLACEMENT

S8229WATLSE3/N	NO-REPLACEMENT
S8512BS9EXL/N	NO-REPLACEMENT
S8512BU	XG84512BS002P
S8529WUSMS/N	NO-REPLACEMENT
S8819BX00036	XG84819BS0030
S8821WX00042	XG84821WS0001
S8822BU	XG84822BS002P
S8822BU-101/N	NO-REPLACEMENT
S8822BX00213	NO-REPLACEMENT
S8822WA-067/N	NO-REPLACEMENT
S8822WA-068/N	NO-REPLACEMENT
S8822WA-080/N	NO-REPLACEMENT
S8822WA-081/N	NO-REPLACEMENT
S8822WA-099/N	NO-REPLACEMENT
S8822WA-100/N	NO-REPLACEMENT
S8822WU9BK/N	NO-REPLACEMENT
S8822WX00131	NO-REPLACEMENT
S8829BAS9/N	NO-REPLACEMENT
S8829WALSE3/N	NO-REPLACEMENT
S8829WALSE4/N	NO-REPLACEMENT
S8829WALSE5/N	NO-REPLACEMENT
S8829WALSE6/N	NO-REPLACEMENT
S8829WATLSE4/N	NO-REPLACEMENT
S8829WU9BK/N	NO-REPLACEMENT
SN88EXTW200/N	NO-REPLACEMENT
S8521WDEL/N	NO-REPLACEMENT
S85222WA-057/N	NO-REPLACEMENT
S85222WA-058/N	NO-REPLACEMENT
S85222WA-060/N	NO-REPLACEMENT
S85223WUMS/N	NO-REPLACEMENT
S85223WUMS2/N	NO-REPLACEMENT
S85223WUSMS/N	NO-REPLACEMENT
S85229WUMS/N	NO-REPLACEMENT
S85229WUMS2/N	NO-REPLACEMENT
S85229WUSMS/N	NO-REPLACEMENT
S8522B	XG84522BS0001
S8522BF	XG84522BS0001
S8522BU	XG84522BS002P
S8522BX00180	XG84522BS00C5
S8522WDEL/N	NO-REPLACEMENT
S8522WSTCS/N	NO-REPLACEMENT
S8522WU-114/N	NO-REPLACEMENT
S8522WX00127	NO-REPLACEMENT
S8523WUMS2/N	NO-REPLACEMENT
S8523WUSMS/N	NO-REPLACEMENT
S8529WUMS/N	NO-REPLACEMENT
S8529WUMS2/N	NO-REPLACEMENT
E6412B2FP	E6412B2

N8122WNNABDIS/N	XG85121WS00Q5
N8212BE	N8212B
N8222BU	N8222B
N8222WU-002/N	N8222WUSP-002/N
N8229BX00047	N8222B
N8512BC	N8512B
N8512WC	N8512B
N8519BC	N8512B
N8522BU	N8522B
N8522W	N8522B
N8529B	N8522B
N8529BU	N8522B
N8529GVTCB/N	NO-REPLACEMENT
N8812BU	N8812B
N8822BE	N8812B
N8822WX00049	NO-REPLACEMENT
N8829BCMDA/N	NO-REPLACEMENT
N8829WCLSE3/N	NO-REPLACEMENT
S6212B	XG64212BS0001
S6222BX00181	XG64222BS0001
S6222WP-003/N	NO-REPLACEMENT
S6222WPSP-003/N	NO-REPLACEMENT
S68EXTW200/N	NO-REPLACEMENT
S7121WSPXC001/N	XG75121WS00FQ
S7123WUDBN5/N	NO-REPLACEMENT
S7222BX00009	NO-REPLACEMENT
S7222WUIISO/N	NO-REPLACEMENT
S7512B	XG74512BS0001
S7512WUDBN/N	NO-REPLACEMENT
S7522BAA/N	NO-REPLACEMENT
S7522WVTCB2/N	NO-REPLACEMENT
S7529WALSE3/N	NO-REPLACEMENT
S7822BU-098/N	NO-REPLACEMENT
S7822WU-096/N	NO-REPLACEMENT
S7822WX00034	XG74822WS002P
S7829WALSE10/N	NO-REPLACEMENT
S7829WALSE5/N	NO-REPLACEMENT
S7829WALSE8/N	NO-REPLACEMENT
S7829WUSBK/N	NO-REPLACEMENT
S8222B	XG84222BS0001
S8222BT2/N	NO-REPLACEMENT
S8222WU	XG84222WS002P
S8222WX00074	NO-REPLACEMENT
S8512B	XG84512BS0001
S8512BX00056	XG84512BS0001
S8522BX00257	NO-REPLACEMENT
S8522WU-112/N	NO-REPLACEMENT
S8523WUMS/N	NO-REPLACEMENT

S8529WALSE3/N

NO-REPLACEMENT