

PRODUCT DISCONTINUATION NOTICE

PDN NO.: IKL2013-001

IXYS Product Type:	Type	Recommended replacement
	KXOB22-12X1	KXOB22-12X1L
	KXOB22-04X3	KXOB22-04X3L
	KXOB22-01X8	KXOB22-01X8L

Reason: Switch from epoxy coating to lamination version in order for improved surface mounting reflow feasibility and higher reliability performance

Last time order date: Aug. 31st, 2013

Last time delivery date: Sep. 30th, 2013

Internal Reference: IKPO_2013_001

In case of any question, please contact

Initiator	Title/Function	Date	e-mail
Bill	MP	Aug. 27th, 2013	b.lee@ixys.net

IXYS Korea Ltd.

AICT 4F, A Dong, 145 Gwanggyo-ro, YeongTong-Gu,
Suwon, GyeongGi-Do, Republic of Korea [443-270]

Phone: +82-31-888-9206

Fax: +82-31-888-9207
