

TE Connectivity

Product Change Notification: E-19-013089 PCN Date: 03-SEP-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

DEUTSCH HD30 Series, Plug and Receptacle Connectors Mod-059 Size 24

Description of Changes

The Industrial and Commercial Transportation business unit of TE Connectivity is changing the standard Package Quantity will change from pack counts as indicated below. Receptacle pack counts will change as follows: from 100 to 80. Product drawings are not affected. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAPs will not be submitted for this change since product fit, form and function is not affected.

HD30 Packaging Change - box before



HD30 Packaging Change - box after



HD30 Packaging Change - parts before



HD30 Packaging Change - parts after



Reason for Changes:

Dear Customer, we hereby inform you of this change. The change is necessary to standardize packaging in the current manufacturing location. The change does not impact connector performance. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

Estimated Dates:

zotiliated Pates.	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	04-DEC-2019
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	28-AUG-2023

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Alias Part Number(s)	-
HD34-24- 18SN-059	NO					
	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
HD36-24- 31SE-059				"ZPF000000000131180", "HD36-24-31SE- 059-LS", "5-1899768-7", "HD36-24-31SE- 059-L"			
HDB36-18- 14SN-059	NO			"ZPF000000000130749"			
HDB36-24- 31SE-059	NO			"ZPF000000000131134", "6-1899773-1"			
HDB36-24- 91SE-059	NO			"ZPF000000000130524", "1-1899783-1"			
HDB36-24- 91SN-059	NO			"ZPF000000000130526", "3-1899777-4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
HD34-24- 18SN-059	NO						
HD36-24- 31SE-059	NO			"ZPF000000000131180", "HD36-24-31SE- 059-LS", "5-1899768-7", "HD36-24-31SE- 059-L"			
HDB36-18- 14SN-059	NO			"ZPF000000000130749"			
HDB36-24- 31SE-059	NO			"ZPF000000000131134", "6-1899773-1"			
HDB36-24- 91SE-059	NO			"ZPF000000000130524", "1-1899783-1"			
HDB36-24- 91SN-059	NO			"ZPF000000000130526", "3-1899777-4"			

Part Number(s) being Modified:

art vulnber(3) being mounted.								
Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference	
HD34-24- 18SN-059	NO							
HD36-24- 31SE-059	NO			"ZPF000000000131180", "HD36-24-31SE- 059-LS", "5-1899768-7", "HD36-24-31SE- 059-L"				
HDB36-18- 14SN-059	NO			"ZPF000000000130749"				
HDB36-24- 31SE-059	NO			"ZPF000000000131134", "6-1899773-1"				
HDB36-24- 91SE-059	NO			"ZPF000000000130524", "1-1899783-1"				
HDB36-24- 91SN-059	NO			"ZPF00000000130526", "3-1899777-4"				