

TE Connectivity

Product Change Notification: P-19-017488 PCN Date: 11-JUN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).


General Product Description:

Suppression of recess holes


Description of Changes

Holes to be suppressed. note: presently, the holes are blind. Making them though holes is not an option, Panasonic required parts shall not have visible holes when accessory is closed.






Proposed design



Metallization default aspect







Reason for Changes:

Product improvement. During the plating process, the holes located next to the screw passage (material recess) can generate brown stains or lack of plating. note: purpose of the holes was to avoid shrinkage marks (suggestion of the molding dpt, during design review, in order to have as constant as possible material thickness.)

Estimated Dates:

| Estimated Dates. | | | | |
|--|--|--|--|--|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | | |
| | 07-OCT-2019 | | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | | |
| | 01-JUN-2020 | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| ZPF000000000204892 | NO | | | "787-8055- 17M" | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| ZPF000000000204892 | NO | | | "787-8055- 17M" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| ZPF000000000204892 | NO | | | "787-8055- 17M" | | | |